

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	18-Oct-08	105

PROJECT POINTS OF CONTACT

Position	Name	E-Mail Address	Phone No.
BRC PROJECT MANAGER	Lee Farris	lfarris@landwellco.com	702-567-0400
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.c	970-260-5886
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolution	720-641-8660

WEATHER CONDITIONS

Conditions				Temp (F)	Wind	Add'l Readings	
AM	Sunny/Clear	PM	Sunny / Party Cloudy	Low 58 High 87	SSE 5mph	Precip. (in Ch.)	Humidity (%)
Additional Weather Comments Calm in AM, Light wind from the South in PM.							

ON-SITE WESTON PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager. CM	Construction Management Services.	N
Dave Goertz	Project Engineer	Construction Management Services.	N
Richard Davis	Project Engineer	Construction Management Services.	Y
Chris White	Assist. Const. Mgr	Construction Management Services.	Y
	Assist. Const. Mgr	Construction Management Services.	
June Laubinger	Admin Assistant	Construction Management Services.	Y

ON-SITE GEOSYNTEC PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	N
Robecca Flynn	Engineer	Oversight	N
Wayne Wofford	QA/QC Tech	Oversight	N
Brent Barbacane	QA/QC Tech	Oversight	N
Camon Liddell	QA/QC Tech	Oversight	Y

ON-SITE SUPPORT PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring.	N
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring.	Y
Jerry Fauchaux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N

OVERSITE PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Scott McKeag, McGinley	Oversight	For NDEP	N
Devin Gordon, McGinley	Oversight	For NDEP	Y
Jennifer Coe, ATC	Field Observation	For AIG	Y
Ron Perry, ASW	Inspector	Liner Inspector	N
PBS&J, Survey	Surveyors	Surveying, QA	N
Brian Rakvica	Inspector	NDEP	N

ON-SITE CONTRACTOR PERSONNEL

Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	N
Timothy Stadt	Entact	Health and Safety Technician	Y
	Entact	26 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	N
Adam Calveledge	Entact	Health & Safety Officer	Y
Rick McIntire	Entact	CSP, Safety	Y
	American Asphalt	1 Equipment operators	Y
	American Asphalt	1 Superintendent	Y
	Environmental Specialties, Inc	Liner Superintendent	N

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	18-Oct-08	105

	Environmental Specialties, Inc.	Laborers/ Seamers	N	
	Kenney Survey	CAMU	N	
	ABC Survey	Eastside/CAMU	N	

ON-SITE EQUIPMENT

Equipment	Vendor / Tag No.	Work Performed				
CAT D400E Dump Truck (2)		CAMU	-	-	-	-
JD D400 Dump Trucks (8)		Eastside		-	-	-
CAT 324D long stick excavator		CAMU	-	-	-	-
CAT D8R Dozer with disc		Eastside		-	-	-
CAT 345 excavator		Eastside		-	-	-
CAT 330 Excavator		Eastside		-	-	-
Case double pan scrapers.		Eastside		-	-	-
CAT D6 LGP Dozer (2)		Eastside				-
Water Trucks (2)		Eastside				-
637/631 Cat Scrapers (6)		CAMU				-
CAT 16H Grader		CAMU				-
CAT D-10 Dozer		CAMU				-
CAT Water Wagon		CAMU				-
CAT D-6 Dozer		CAMU				-
CAT 14H Grader		CAMU				-
Gradall		CAMU				-
JLG		CAMU				-
IR Smooth drum Roller		CAMU, Phase 1				-
Tenent Street Sweeper		Eastside and CAMU				-
Bomag Smooth drum Roller		CAMU, Phase 1				-
						-
						-

MATERIAL HANDLING (ON-SITE DELIVERY / REMOVAL)

Material	Vendor	Today	UOM	Purpose	Delivery Verification			
					to date	Qty	Spec	Tags
GCL	CETCO	0	rolls	For CAMU, On site		207		
Geocomposite	Agru	0	rolls	For CAMU, On site		194		
Geomembrane	Agru	0	rolls	For CAMU, On site		37		

WORK COMPLETED

Description of Work Executed Today

Eastside Mixing and Drying Activity:

- 324 CAT excavator, decontaminating.
- Welding 4" HDPE pipe for sprinkler system.
- Conducted dust monitoring.
- Performed decontamination of equipment.
- Installing tarps on haul trucks

CAMU Activity:

Excavation .

- Phase II continued screening soils and placing lifts on floor. Continued working on south slopes.
- Hauled western ditch soils and place into Phase 1.
- Western ditch soils hauled into Phase 1. Day Shift: 97 loads @ 22 cy/loads = 2,134 cy (2) trucks.
- Western ditch soils hauled into Phase 1. Night Shift: 0 loads @ 22 cy/loads = 0 cy (0) trucks..
- (1) D6 dozer placed western ditch soils in 12" lift. Followed by (1) vibratory rollers compacting (3) complete passes in Phase 1.
- (1) D6 dozer worked on grading floor of phase 2, western ditch.
- Laborers sized woven geotextile for placement.
- Conducted dust monitoring.

Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cumulative embankment placed: 0 cy

Waste Placement

- Phase 1 estimated daily waste placed: 97 loads @ 22cy/load = 2,134 cy
night shift placed: 0 loads @ 22cy/load = 0 cy
- Phase 1 estimated cumulative waste placed: 101,566 cy. Western Ditch Soils
- Phase 1 Operations Layer placed. completed. Cumulative total: 21,662

Geosynthetics. Estimated cumulative installed quantity by Phase.

- Phase 1 GCL placed: 0 sf daily, 307,372 sf cumulative.
- Phase 1 Geomembrane: 0 sf daily, 307,372 sf cumulative
- Phase 1 Geocomposite: 0 sf daily, 307,372 sf cumulative.
- Phase 1 Geotextile: (0) sf daily, 69,340 sf cumulative.

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	18-Oct-08	105

Other:

HEALTH & SAFETY

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted	
1	1. Inspected the construction site for safety hazards. Found that the workers were not wearing proper safety gear (hard hats, safety glasses, and gloves). I immediately stopped the work and instructed them to wear the correct equipment. I also found that the scaffolding was not properly secured, so I had it dismantled and re-erected correctly.
2	2. Conducted a safety inspection of the electrical system. Found that the wiring was outdated and potentially hazardous. I had the electrician replace the old wiring with new, code-compliant wiring. I also found that the ground fault circuit interrupter (GFCI) was not working, so I had it replaced.
3	3. Inspected the fire safety equipment. Found that the fire extinguishers were expired and the fire alarm system was not functioning properly. I had the fire extinguishers replaced and the fire alarm system repaired.
4	4. Conducted a safety inspection of the construction site. Found that the workers were not wearing proper safety gear (hard hats, safety glasses, and gloves). I immediately stopped the work and instructed them to wear the correct equipment. I also found that the scaffolding was not properly secured, so I had it dismantled and re-erected correctly.
5	5. Inspected the construction site for safety hazards. Found that the workers were not wearing proper safety gear (hard hats, safety glasses, and gloves). I immediately stopped the work and instructed them to wear the correct equipment. I also found that the scaffolding was not properly secured, so I had it dismantled and re-erected correctly.
6	6. Conducted a safety inspection of the construction site. Found that the workers were not wearing proper safety gear (hard hats, safety glasses, and gloves). I immediately stopped the work and instructed them to wear the correct equipment. I also found that the scaffolding was not properly secured, so I had it dismantled and re-erected correctly.
7	7. Inspected the construction site for safety hazards. Found that the workers were not wearing proper safety gear (hard hats, safety glasses, and gloves). I immediately stopped the work and instructed them to wear the correct equipment. I also found that the scaffolding was not properly secured, so I had it dismantled and re-erected correctly.
8	8. Conducted a safety inspection of the construction site. Found that the workers were not wearing proper safety gear (hard hats, safety glasses, and gloves). I immediately stopped the work and instructed them to wear the correct equipment. I also found that the scaffolding was not properly secured, so I had it dismantled and re-erected correctly.
9	9. Inspected the construction site for safety hazards. Found that the workers were not wearing proper safety gear (hard hats, safety glasses, and gloves). I immediately stopped the work and instructed them to wear the correct equipment. I also found that the scaffolding was not properly secured, so I had it dismantled and re-erected correctly.
10	10. Conducted a safety inspection of the construction site. Found that the workers were not wearing proper safety gear (hard hats, safety glasses, and gloves). I immediately stopped the work and instructed them to wear the correct equipment. I also found that the scaffolding was not properly secured, so I had it dismantled and re-erected correctly.

Entact H&S Tailgates

Safety Topic Eastside: Discussed procedures if lightning is spotted in the area.

Safety Topic CAMU: Discussed procedures if lightning is spotted in the area..

Rick McIntire, CSP on site covering for Joe Curila.

Safety Incidents: None.

Dust Incidents: None.

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

Description of Quality Control Actions Taken Today / Quality Inspections Conducted	
1	1. Inspected 10 units of Product A for defects. Found 2 units with minor surface scratches. No action required.
2	2. Inspected 15 units of Product B for assembly errors. Found 3 units with missing screws. Re-worked and re-inspected.
3	3. Inspected 20 units of Product C for packaging damage. Found 1 unit with cracked box. Replaced box and re-inspected.
4	4. Inspected 5 units of Product D for color consistency. Found 1 unit with slight discoloration. Re-worked and re-inspected.
5	5. Inspected 12 units of Product E for functionality. Found 1 unit with non-responsive button. Replaced button and re-inspected.
6	6. Inspected 8 units of Product F for material quality. Found 1 unit with weak joint. Re-worked and re-inspected.
7	7. Inspected 18 units of Product G for labeling accuracy. Found 2 units with incorrect labels. Re-labeled and re-inspected.
8	8. Inspected 10 units of Product H for safety features. Found 1 unit with missing safety cap. Replaced cap and re-inspected.
9	9. Inspected 14 units of Product I for finish quality. Found 1 unit with uneven finish. Re-worked and re-inspected.
10	10. Inspected 16 units of Product J for component quality. Found 1 unit with faulty component. Replaced component and re-inspected.

Daily CQA Summary..

Monitored site haul road maintenance and construction of new 12" capped haul roads.

Monitored waste relocation and placement from the western ditch into Phase 1. Monitored proof rolling.

Monitor screening and placement as well as slope regrading of native soils in Phase II.

Continue updating project documents and database to facilitate reporting.

ISSUES AND/OR ITEMS OF DISCUSSION

Discussion of Issues / Concerns / Conversations / Topics

SITE VISITORS

[illegible]

Report Prepared By / Title	Date Prepared	Signature
----------------------------	---------------	-----------

Dick Laubinger, Construction Manager 18-Oct-08

Date Prepared

Signature

18-Oct-08

Signature _____

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	18-Oct-08	105


DAILY PHOTO LOG

Photo 1



Eastside: SW-12. Crust over water.

Photo 2



CAMU: Phase 1. Ramp.

Photo 3



CAMU: Phase 2. Western ditch grading the floor.

Photo 4



CAMU: Phase 2. Western ditch grading floor.