Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



DAILY PRODUCTION & QUALITY CONTROL REPORT Project No./Contract No. Project Title / Location Day of Report Report No. BRC Eastside Common Areas Soils Remediation 6389 03-Dec-08 147

PROJECT POINTS OF CONTACT							
Position	Name	E-Mail Address	Phone No.				
BRC PROJECT MANAGER	Lee Farris, On Site.	Ifarris@landwellco.com	702-567-0400				
BRC PROJECT MANAGER	Ranajit Sahu, On Site.	sahuron@earthlink.net	702-567-0400				
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.c	970-260-5886				
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolution	720-641-8660				

Conditions			Temp (F)		Wind		Add'l Readings		
AM	Owner / Barty Olavelle	PM Sunny / Party Cloudly	Oursey / Bests Olessells		41			Precip. (In/Dy.)	
AW	Sunny / Party Cloudly	PIN	Sunny / Party Cloudly	High	63	ESE	5mph	Humidity (%)	

0 mph, in AM. 5 mph in PM.

ON-SITE WESTON PERSONNEL						
Name	Position	Trade / Work Performed	Y/N			
Dick Laubinger	Construction Manager	Construction Management Services.	Y			
Dan Brennecke	Project Manager. CM	Construction Management Services.	N			
Richard Davis	Project Engineer	Construction Management Services.	Υ			
Chris White	Assist. Const. Mgr	Construction Management Services.	Y			
Wayne Hodgson	Assist. Const. Mgr	Construction Management Services.	Y			
Kevin Cooke	Assist. Const. Mgr	Construction Management Services.	Y			
June Laubinger	Admin Assistant	Construction Management Services.	Y			

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	Y
Robecca Flynn	Engineer	Oversight	N
Wayne Wofford	QA/QC Tech	Oversight	Y
Roland Derosier	QA/QC Tech	Oversight	Y
Camon Liddell	QA/QC Tech	Oversight	Y
Jeremy Osborn	QA/QC Tech	Oversight	Y

Name	Position	Trade / Work Performed	Y/N	
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	N	
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	Y	
Jerry Faucheux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N	

OVERSITE PERSONNE		上海南 15 20 15 15 15 15 15 15 15 15 15 15 15 15 15	
Name	Position	Trade / Work Performed	Y/N
Mark Eizman, ASW	Inspector	Liner Inspector	Υ
Devin Gordon, McGinley	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Joe Ludlow, ASW	Inspector	Liner Inspector	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
Brian Rakvica	Inspector	NDEP, Site visit	N
PBS&J, Survey	Surveyors	Surveying, QA	N
ON-SITE CONTRACTOR	PERSONNEL		
	THE RESERVE AND ADDRESS OF THE PARTY OF THE		

Steve Morrow, ASW	Inspector	Liner inspector	N		
Brian Rakvica	Inspector	NDEP, Site visit	N		
PBS&J, Survey	Surveyors	Surveying, QA	N		
ON-SITE CONTRACTO	R PERSONNEL				
Name	Company	Trade / Work Performed	Y/N		
Erik Geringer	Beringer Entact Project Manager		Y		
Josh Carrol	Entact	Asst Project Manager	Y		
Russ Karnes	Entact	Eastside, Superintendent	Y		
Michael Carlson	Entact	Engineer	Y		
Joe Curilla	Entact	Health & Safety Officer	N		
Timothy Stadt	Entact	Health and Safety Technician	Y		
	Entact	26 Equipment Operators & Truck Drivers	Y		
Ed Long	Entact	CAMU, Superintendent	Y		
Lance Bruce	Entact	Health & Safety Officer	Y		
Terry Harper	Entact	CAMU, Superintendent	Y		
Rick McIntire	Entact	CSP, Safety	Y		
Dale Walsh	Converse	CSP, Safety			

Ver 1.1 11/07 1 of 4

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	03-Dec-08	147
		03-Dec-08	147

Eli Blackburn	Entact	Asst Project Manager	Y
	Environmental Specialties,Inc	1 Liner Superintendent	Y
	Environmental Specialties,Inc Environmental Specialties,Inc	12 Laborers/ Seamers	Y
	Kenney Survey	CAMU	N N
	Kenney Survey ABC Survey	Eastside/CAMU	Y
	,		

ON-SITE EQUIPMENT						
Equipment	Vendor / Tag No.	Work Performed				
CAT D400E Dump Truck (2)		CAMU	-	-	-	
JD D400 Dump Trucks (8)		Eastside		-	-	
CAT 324D long stick excavator		CAMU	-	-	-	
CAT D8R Dozer with disc		Eastside		-	-	
CAT 345 excavator		Eastside		-	-	
CAT 330 Excavator		Eastside		-	-	
Case double pan scrapers.		Eastside		-	-	
CAT D6 LGP Dozer (2)		Eastside				
Water Trucks (2)		Eastside				
637/631 Cat Scrapers (6)		CAMU				
CAT 16H Grader		CAMU				
CAT D-10 Dozer		CAMU				
CAT Water Wagon		CAMU				
CAT D-6 Dozer		CAMU				
CAT 14H Grader		CAMU				
Gradall		CAMU				
JLG		CAMU				
IR Smooth drum Roller		CAMU, Phase 1				
Tenent Street Sweeper		Eastside and CAMU				
Bomag Smooth drum Roller		CAMU, Phase 1				
Chieftain 1400 Powerscreener		Eastside, screening 1" minus				

MATERIAL HANDLING (ON-SITE DELIVERY / REMOVAL)								
Material	Vendor	Today	UOM	Purpose	Delivery Verifica		ion	
material	vendoi	Today	OOM	Fulpose	to date Qty	Spec	Tags	
GCL	CETCO	0	rolls	For CAMU, On site	506			
Geocomposite	Agru	0	rolls	For CAMU, On site	599			
Geomembrane	Agru	0	rolls	For CAMU, On site	192			

WORK COMPLETED

Eastside Mixing and Drying Activity:

- Continued screening moisture conditioned material using powerscreener, (PUB-4).
- Continued moving sprinklers to PUC-3...
- Worked on tarps and rails for haul trucks.
- Continued hauling 1" minus material to phase II for operations layer.

CAMU Activity:

- ESI continued installing geocomposite and woven geotextile in Phase II.
- Continued backfill and compaction of anchor trench in Phase II.
 Continued grading North BMI Landfill.
 Continued grading operations layer in Phase II.

- Night Shift:
- Continued placing operations layer in Phase II.

Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy

Waste Placement

- Phase 1 estimated daily waste placed: 0 loads @ 20cy/load = 0 cy.
- night shift placed: 0 loads @ 20cy/load = 0 cy.
 Phase 1 estimated cummulative waste placed: 210,538 cy. Western Ditch, NE Equilization, Eastside beta stockpile and PUA-4.PUB-3.
 Phase 1 Operations Layer placed. completed. Cumulative total: 21,662

2 of 4

- Phase 2 estimated night shift placed: 177 loads @ 20cy/load = 3,540 cy. (14 trucks hauling).
- Phase 2 Operations Layer placed. daily: 3,540 cy. Cumulative total: 24,700 cy.

Geosynthetics. Estimated cummulative installed quantity by Phase. Dhage 1 COL placed to of dollar 207 270 of as

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	03-Dec-08	147
		03-Dec-08	147

- Phase 1 GCL placed:0 sf daily, 307,372 sf cummulative.

- Phase 1 Geomembrane:0 sf daily, 307,372 sf cummulative

Phase 1 Geocomposite: 0 sf daily, 307,372 sf cummulative.

- Phase 1 Geotextile: (0) sf daily. 69,340 sf cummulative.

-Phase 2 GCL placed: (0) sf daily, 498,468 sf cummulative. -Phase 2 Geomenbrane: (0) sf daily, 498,468 sf cummulative. -Phase 2 Geocomposite: (90,000) sf daily, 515,000 sf cummulative.

Other:

ш	EA	LTI	4 9	2. C	ΛE	ETY

Entact H&S Tallgates
Safety Topic: Eastside: Remote worker, use buddy system when possible.

Safety Topic: CAMU, Day: Discussed not working down-slope of equipment.

Eastside and CAMU, Night shift: Truck drivers speed and conditions of roadways paved and unpaved, be aware.

Safety Incidents: None. Dust Incidents: None.

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

<u>Daily CQA Summary</u>.

Monitored waste material placement in Phase II as operations layer, (night shift).

Monitored installation of geosynthetics in Phase II.

Monitored BMI North subgrade preparation.

Continue review of and updating of project documents and database to facilitate reporting.

Performed compaction testing of anchor trench around phase II.

	the forest to be being			
ISSHES	AND/OR	ITEMS	OF DISC	CUSSION

Discussion	of	lssues /	Concerns	/ Conversations /	Topics

TE VISITORS						
Name	Organization	Purpose of Visit				
		*				
					-	
					_	

Report Prepared By / Title

Dick Laubinger, Construction Manager

3-Dec-08

Ver 1.1 11/07 3 of 4

Basic Remediation Company 875 West Warm Springs Road

Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	03-Dec-08	4.47
0	0	03-Dec-06	147

DAILY PHOTO LOG

Photo 1




Photo 2



CAMU: BMI North Subgrade in preparation looking Southeast.

Photo 3



CAMU: Phase II, Geocomposite installed looking Southeast at Phase IIIA bench.

Photo 4



Ver 1.1 11/07 4 of 4