## Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



### **DAILY PRODUCTION & QUALITY CONTROL REPORT** Project No./Contract No. Day of Report Report No. Project Title / Location 6389 **BRC Eastside Common Areas Soils Remediation** 47 13-Aug-08

PROJECT POINTS OF CONTACT							
Position	Name	E-Mail Address	Phone No.				
BRC PROJECT MANAGER	Lee Farris	lfarris@landwellco.com	702-567-0400				
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400				
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.	970-260-5886				
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolutio	720-641-8660				

	R CONDITIONS						_	
	0	Conditions		Tem	p (F)	W	ind	Add'l Readings
AM	Summi/Clone	PM	Supply / Bady Cloudly	Low	80			Precip. (InDy.)
Am	Sunny/Clear	1-14	Sunny / Party Cloudly	High	106	sw	5mph	Humidity (%)

		Conditions		Ten	1p.(F)	W	find	Add'l	Readings	
AM	SuppulClass	PM Su	inny / Party Cloudly	V		Precip. (may)				
Am	Sunny/Clear	Phi St	inny / Party Cloudly	High	106	sw	5mph	Humidity (%)		
dditional V Calm to 5	Weather Comments 5 mph.	O.								
ON-SITE	WESTON PERSO									
	Name	Position		Tra	de/Worl	k Perfor	med		Y/N	
Dick Laub	oinger	Construction Manager	Construction M	lanagen	nent Sen	vices.			Y	
Dan Brenn	necke	Project Manager. CM	Construction M	Construction Management Services.						
Dave Gerl	tz	Project Engineer	Construction M						Y	
June Laut	binger	Admin Assistant	Construction M	lanagem	nent Ser	vices.			Y	
ON-SITE	GEOSYNTEC PE	RSONNEL			1, 60					
	Name	Position		Tra	de / Wor	k Parlo	med		YAN	
Wayne W	offord	QA/QC Tech	Oversight						Y	
Brent Bark	1.00-40-513.00	QA/QC Tech	Oversight						Ý	
Jim Cox		QA/QC Supervisor	Oversight						Y	
Greg Cord	coran	Engineer of Record	Oversight						N	
Robecca I	Flynn	Engineer	Oversight						Y	
Camon Li	iddell	QA/QC Tech	Oversight						Y	
ON-SITE	SUPPORT PERS	ONNEL								
	Name	Position		Tro	da / Wor	k Parlo	rmed		YAN	
the second second second second	locker, Tetra Tech	Air Monitoring Specialist	Air Monitoring						Y	
	no, Tetra Tech	Air Monitoring Specialist	Air Monitoring						Y	
	cheux, Tetra Tech tions, BRC	Air Monitoring Specialist BRC, QA Oversight	Air Monitoring Site Monitoring	-					Y	
OVERSI	TE PERSONNEL Name	Position		Test	de Wor	k Parlo	rmad	-	YIN	
Scott Mak	Keag, McGinley	Oversight	For NDEP		140		inco		Y	
	rdon, McGinley	Oversight	For NDEP						Y	
Dock Kim		Field Observation	For AIG			_			Y	
Ron Perry	M111000	Inspector	For NDEP, CA	MU Sub	orade a	nd Line	r Inspe	ction	N	
PBS&J, S		Surveyors	1.57 (1.56.1.1.57.)		3,440	10,2110	поро		N	
ON-SITE	CONTRACTOR					L 10				
	Name	Company			ide/Wor	K Parto	rmed		Y/N	
Erik Gerin		Entact	Project Manag						Y	
Josh Carr		Entact	Asst Project M						Y	
		Entact	Eastside, Supe	erintende	ent				Y	
According to the latest terminal and		Entact Entact	Engineer Health & Safe	tu Offic-					Y	
Michael C	rea .		Health and Sale						Y	
Michael C Joe Curilla	Parker	Inntact	i iodilii dilu Sa			ck Driv	ers		Y	
Michael C Joe Curilla	Parker	Entact	18 Equipment		- w 110	JH 2114	-10			
Michael C Joe Curilli Michael P	Parker	Entact	18 Equipment CAMU, Superi		t				Y	
Michael C Joe Curilli Michael P	Parker	Entact Entact	CAMU, Superi	ntenden					Y	
Michael C Joe Curilli Michael P	Parker	Entact Entact American Asphalt	CAMU, Superi Earthwork Sup	ntenden erintend	lent	ck Driv	vers,		Y	
Michael C Joe Curilli Michael P Ed Long		Entact Entact	CAMU, Superi Earthwork Sup 11 Equipment	ntenden erintend	lent	ck Driv	rers,			
Michael C Joe Curill Michael P Ed Long	ntire	Entact Entact American Asphalt American Asphalt	CAMU, Superi Earthwork Sup	ntenden erintend	lent	ck Driv	vers,		Y	
Michael C Joe Curill Michael P Ed Long	ntire	Entact Entact American Asphalt American Asphalt Entact KDC Company	CAMU, Superi Earthwork Sup 11 Equipment CSP, Safety	ntenden perintend Operato	lent	ck Driv	rers,		Y Y Y N	
Michael C Joe Curill Michael P Ed Long	ntire	Entact Entact American Asphalt American Asphalt Entact KDC Company Environmental Specialties	CAMU, Superi Earthwork Sup 11 Equipment CSP, Safety	ntenden perintend Operato endent	lent	ck Driv	vers,		Y Y Y N	
Russ Karr Michael C Joe Curilli Michael P Ed Long Rick McIn Don Cadv	ntire	Entact Entact American Asphalt American Asphalt Entact KDC Company	CAMU, Superi Earthwork Sup 11 Equipment CSP, Safety	ntenden perintend Operato endent	lent	ck Driv	vers,		Y Y Y N	

Ver 1.1 11/07 1 of 4

## **DAILY PRODUCTION & QUALITY CONTROL REPORT** Project No./Contract No Day of Report Report No. 6389 **BRC Eastside Common Areas Soils Remediation** 13-Aug-08 47

Equipment	Vendor/Tag No.		Work Performed				
CAT D400E Dump Truck (1)		Eastside		-			
JD D400 Dump Trucks (4)		Eastside					
CAT 324D long stick excavator		CAMU					_
CAT D8R Dozer with disc		Eastside					
CAT 345 excavator		Eastside					
CAT 330 Excavator		Eastside					
Case double pan scrapers.		Eastside					- 8
CAT D6 LGP Dozer (2)		Eastside					
Water Trucks (2)		Eastside					
637/631 Cat Scrapers (6)		CAMU					
CAT 16H Grader		CAMU					
CAT D-10 Dozer		CAMU					
CAT Water Wagon		CAMU					
CAT D-6 Dozer		CAMU					
CAT 14H Grader		CAMU					
Gradall		CAMU					
Bobcat Skidsteer		CAMU					
JLG		CAMU					
CAT D4 dozer		CAMU					
MATERIAL HANDLING (ON-S	TE DELIVERY / REMOVAL)						
Material	Vendor	QTY UO	M Purpose	D	elivery V	rification	

For CAMU

For CAMU

0 rolls For CAMU

0 rolls

0 rolls

Woven Geotextile								
WORK COMPLETED								

GCL

Geocomposite

## Eastside Mixing and Drying Activity;

- Loading out wet material from SW-4 using 345 excavator. (4) haul trucks hauling to beta ditch stockpile. 214 loads, (4,280) cy.
   Leveled material from SW-4 on staging area and beta ditch using D6 dozer..
   D8 Dozer disking wet pond material that is spread over the dry ponds.

CETCO

Agru

- Versatile tractor and pans transporting dried material from various ponds and spreading at stockpile. 0 loads, () cy. Out of Service.
- SW-6, 345 excavator loading out additional discolored soils below liner. (0) loads = (0) cy. No Activity.
- Sewer Realignment Remediation scraping (13) loads, (286) cy. 1 truck.

## CAMU Activity:

## Excavation

- Phase 2 Excavation. 631/637 scrapers (3,000) cy 3 scrapers.
- -Western Ditch, continue screening operation.
- Entact maintained 12" clean soil cap over west haul rd and bypass rd.
- Phase 2, Entact excavated two additional potholes trenches on floor.
- Phase 2, GES took water samples in floor sump trench.

## Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy

## **Waste Placement**

- Phase 1 estimated daily waste placed: 0 cy
- Phase 1 estimated cummulative waste placed: 0 cy

## Geosynthetics

- Phase 1 Liner, ESI completed the installation of GCL and Geomembrane in CAMU Phase 1.
- Phase 1 GCL placed: 2800 sf daily, 347,067 sf cummulative
- Phase 1 Geomembrane:5632 sf daily, 365,136 sf cummulative
- Phase 1 Geocomposite: 66,150 sf daily, 66,150 sf cummulative Phase 1 Geotextile: 0 sf daily, 0 sf cummulative

Other: Sewer Realignment: Remediation work with excavator on floor continued, GES took samples.

## DAILY PRODUCTION & QUALITY CONTROL REPORT Project No./Contract No. Day of Report Report No. 6389 **BRC Eastside Common Areas Soils Remediation** 13-Aug-08 47

Perimeter Fence Inspection and Repair.

## **HEALTH & SAFETY**

ety Actions Taken Today / Safety Inspections Conducted

Entact H&S Tailgates
Morning: Visitors and people on site be aware.

ESI, Liner Crew: Working around spreader bar while deploying liner. Stay in front of operator at all times.

Afternoon: Hydration, drink fluids.

American Asphalt Tailgates

Morning: Site traffic and Visitors...

Safety Incidents: None.

## QUALITY CONTROL

## **Daily CQA Summary**

Monitored installation of GCL and Liner final panels on floor...

Liner Crew performed QC testing on liner. Inspected 12\* capped haul roads for degradation. All areas ok.

Dust: Met requirements.

## **Deviations from CQA Plan**

## ISSUES AND/OR ITEMS OF DISCUSSION

Conducted Weekly Progress Meeting.

CAMU: Burrowing Owls area, Sighting again today (3).

Name	Organization	Purpose of Visit		
Kyle Hansen	GES	CAMU, Phase 2, water sampling in sump trench		$\rightarrow$
Monty	GES	Eastside, Soil sampling, Sewer realignment		
				-
				-
			1	
				_

Report Prepared By / Title

Date Prepared

Signature

Dick Laubinger, Construction Manager

13-Aug-08

# Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

## **DAILY PRODUCTION & QUALITY CONTROL REPORT**

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	13-Aug-08	47
0	0	13-Aug-06	47

## DAILY PHOTO LOG

Photo 1



CAMU, Phase 1 liner completion of geomembrane.

## Photo 2



CAMU, Phase 1, beginning of geocomposite layer.

## Photo 3



CAMU, Phase 2, pothole trench on floor North side..

## Photo 4



CAMU, Phase 2, slope excavation.