

DAILY PRODUCTION & QUALITY CONTROL REPORT						
Project No./Contract No.	Project Title / Location	Day of Report	Report No.			
6389	BRC Eastside Common Areas Soils Remediation	27-Aug-08	59			

PROJECT POINTS OF CO	NTACT	PROJECT POINTS OF CONTACT					
Position	Name	E-Mail Address	Phone No.				
BRC PROJECT MANAGER	Lee Farris, On Site.	lfarris@landwellco.com	702-567-0400				
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400				
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.	970-260-5886				
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolutio	720-641-8660				

	-	40.000		142000	erren en	100		W. S. 104 No
	Condi	tions		15W	b (E)	W	nd	Add'l Readings
AM	Sunny / Party Cloudly	DA	Supply / Borty Cloudly	Low	79			Precip. (mDy.)
Am	Sunny / Party Cloudly	arty Cloudly PM Sunny / Party Clo	Sunny / Party Cloudly	High	104	ENE	3mph	Humidity (%)

Calm to Light Wind..

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager, CM	Construction Management Services.	Y
Dave Gertz	Project Engineer	Construction Management Services.	Y
June Laubinger	Admin Assistant	Construction Management Services.	Y
Linda Nations	Asst Const Manager	Construction Management Services	Y

Name	Position	Trade / Work Performed	Y/N
Wayne Wofford	QA/QC Tech	Oversight	Y
Brent Barbacane	QA/QC Tech	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	N
Greg Corcoran	Engineer of Record	Oversight	N
Robecca Flynn	Engineer	Oversight	Y
Camon Liddell	QA/QC Tech	Oversight	N
Dan Street	QA Manager	Oversight	Y
ON-SITE SUPPORT PERS	ONNEL		
Name	Position	Trade / Work Performed	Y/N
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	N
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	Y
Jerry Faucheux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	Y
OVERSITE PERSONNEL			

Name	Position	Trade / Work Performed	YN
Scott McKeag, McGinley	Oversight	For NDEP	N
Devin Gordon, McGinley	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Ron Perry, ASW	Inspector	Liner Inspector	N
PBS&J, Survey	Surveyors		N

44-	12/7/25/25/25	SECURE CONTRACTOR OF THE PROPERTY OF THE PROPE	4.000
Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	Y
Michael Parker	Entact	Health and Safety Technician	Y
	Entact	22 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	Y
	American Asphalt	Earthwork Superintendent	Y
	American Asphalt	11 Equipment Operators & Truck Drivers,	Y
Rick McIntire	Entact	CSP, Safety	Y
	Environmental Specialties,Inc	Liner Superintendent	N
	Environmental Specialties,Inc	1 Liner Seamer on site.	Y
	Kenney Survey	CAMU	Y

Ver 1.1 11/07 1 of 4

Project No./Contract No.	Project Title / Location	Day of Report	Report No	
6389	BRC Eastside Common Areas Soils Remediation	27-Aug-08	59	
			\equiv	
	,			

Equipment	Vendor / Tag No.		Work Performed		_		
CAT D400E Dump Truck (2)		CAMU		-		-	
JD D400 Dump Trucks (6)		Eastside					
CAT 324D long stick excavator		CAMU		-			- 8
CAT D8R Dozer with disc		Eastside					- 5
CAT 345 excavator		Eastside					- 6
CAT 330 Excavator		Eastside					
Case double pan scrapers.		Eastside					
CAT D6 LGP Dozer (2)		Eastside					
Water Trucks (2)		Eastside					R
637/631 Cat Scrapers (6)		CAMU					- 0
CAT 16H Grader		CAMU					- 5
CAT D-10 Dozer		CAMU					7
CAT Water Wagon		CAMU					
CAT D-6 Dozer		CAMU					
CAT 14H Grader		CAMU					
Gradall		CAMU					
Bobcat Skidsteer		CAMU					
JLG		CAMU					-
CAT D4 dozer		CAMU					
							16
MATERIAL HANDLING (ON-S	ITE DELIVERY / REMOVAL)			100			
Material	Vendor	OTY UOM	Purpose		elivery V	erification	

MATERIAL HANDLING	G (ON-SITE DELIVERY / REMOVAL)						
Material	Vendor	OTY	UOM	Purpose	Condia	Oto	Verificatio Soec	Taga
GCL	CETCO	0	rolls	For CAMU	2000000	1917	Sport	Tanga
Geocomposite	Agru	0	rolls	For CAMU				
Woven Geotextile		0	rolls	For CAMU				

WORK COMPLETED

Eastside Mixing and Drying Activity:

- Eastside Mixing and Drying Activity:

 Loading out prepared material from CTR-2 using 345 excavator. (4) haul trucks hauling to beta ditch. 188 loads, (3,760) cy.

 D6 dozer spread prepared soils at the beta ditch.

 D8 Dozer continued disking operation.

 Versatile tractor and Pans. 0 loads, (0) cy. No Activity.

- Motorgrader maintaining roads. Water truck managing dust control.
- Continued pumping water from SC-1 to SW-12.

CAMU Activity:

Excavation

- Northwest Detention Basin excavation 631/637 scrapers (1,200) cy.
- -Western Ditch. Power screener screening operations layer.
- Entact maintained 12* clean soil cap over west haul rd and bypass rd. Continued Anchor trench backfill and compaction.

Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy

Waste Placement

- Phase 1 estimated daily waste placed: 0 cy
- Phase 1 estimated cummulative waste placed: 0 cy
- Phase 1 Operations Layer placed daily 50 loads, (900) cy

Geosynthetics

- Phase 1. Shovel out silt and debri clean liner and install toe drain at east slope toe.
- Phase 1 GCL placed: 0 sf daily, 347,067 sf cummulative.
- Phase 1 Geomembrane:0 sf daily, 365,136 sf cummulative
- Phase 1 Geocomposite: 0 sf daily, 327,600 sf cummulative.
- Phase 1 Geotextile: (0) sf daily..

Other: Grading at Sewer realignment corridor crossroad.

Ver 1.1 11/07 2 of 4

Project No. Contract No.	Project Title / Location	Day of Report	Report No
6389	BRC Eastside Common Areas Soils Remediation	27-Aug-08	59

Perimeter Fence Inspection and Repair.

HEALTH & SAFETY

escription of Health & Safety Actions Taken Today / Safety Inspections Conducted

Entact H&S Tailgates
Morning: Slips, trip and falls. Night work.
ESI, Liner Crew: Off Site.

Afternoon: Hydration, high temperatures.

American Asphalt Tailgates

Morning: Slips, trips and falls.

Safety Incidents: No Incidents.

QUALITY CONTROL

<u>Daily CQA Summary.</u> Inspected 12" capped haul roads for degradation. All areas ok.

2am start of operations layer placement on liner, halted at 11:50 am.. Wrinkles beginnning.

ESI on site to handle minor repairs. Inspected LCRS pipe for silt, no damage. Contractor to flush out piping.

Dust: Met requirements.

Deviations from CQA Plan

ISSUES AND/OR ITEMS OF DISCUSSION

CAMU: Burrowing Owls, No sighting...

CAMU: Phase 1 night work began, 2 AM placing operations layer at cooler temperatures.

Weekly Progress Meeting held at BRC Offices.

VISITORS			
Name	Organization	Purpose of Visit	

Report Prepared By / Titla

Signature

Dick Laubinger, Construction Manager

27-Aug-08

3 of 4 Ver 1.1 11/07

Basic Remediation Company


875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	27-Aug-08	59
0	0		

DAILY PHOTO LOG





CAMU, Ditch on West side to stop run in to Phase 1...

Photo 2



CAMU: Ditch on South side to stop run in to Phase 2.

Photo 3



Eastside. Fence installation at crossroad sewer realignment.

Photo 4



CAMU, Phase 1 East slope coverage of operations layer.

Ver 1.1 11/07 4 of 4