

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	11-Dec-08	155

PROJECT POINTS OF CONTACT

Position	Name	E-Mail Address	Phone No.
BRC PROJECT MANAGER	Lee Farris	lfarris@landwellco.com	702-567-0400
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.com	970-260-5886
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolution.com	720-641-8660

WEATHER CONDITIONS

Conditions				Temp (F)	Wind	Add'l Readings	
AM	Sunny/Clear	PM	Sunny/Clear	Low 39		Precip. (in)	
				High 60	N 5mph	Humidity (%)	

Additional Weather Comments
 0 mph, in AM. 5 mph in PM.

ON-SITE WESTON PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager, CM	Construction Management Services.	N
Richard Davis	Project Engineer	Construction Management Services.	Y
Chris White	Assist. Const. Mgr	Construction Management Services.	Y
Wayne Hodgson	Assist. Const. Mgr	Construction Management Services.	Y
Kevin Cooke	Assist. Const. Mgr	Construction Management Services.	Y
June Laubinger	Admin Assistant	Construction Management Services.	Y

ON-SITE GEOSYNTEC PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	N
Robecca Flynn	Engineer	Oversight	N
Wayne Wofford	QA/QC Tech	Oversight	Y
Roland Derosier	QA/QC Tech	Oversight	Y
Camon Liddell	QA/QC Tech	Oversight	Y
Jeremy Osborn	QA/QC Tech	Oversight	Y

ON-SITE SUPPORT PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring.	N
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring.	Y
Jerry Fauchaux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N

OVERSIGHT PERSONNEL

Name	Position	Trade / Work Performed	Y/N
Mark Eizman, ASW	Inspector	Liner Inspector	Y
Devin Gordon, McGinley	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Joe Ludlow, ASW	Inspector	Liner Inspector	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
Brian Rakvica	Inspector	NDEP	N
PBS&J, Survey	Surveyors	Surveying, QA	N

ON-SITE CONTRACTOR PERSONNEL

Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	Y
Timothy Stadt	Entact	Health and Safety Technician	Y
	Entact	26 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	Y
Lance Bruce	Entact	Health & Safety Officer	Y
Terry Harper	Entact	CAMU, Superintendent	Y
Rick McIntire	Entact	CSP, Safety	N
Dale Walsh	Converse	CSP, Safety	Y

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	11-Dec-08	155

Eli Blackburn	Entact	Asst Project Manager	Y
	Environmental Specialties, Inc	1 Liner Superintendent	Y
	Environmental Specialties, Inc	12 Laborers/ Seamers	Y
	Kenney Survey	CAMU	N
	ABC Survey	Eastside/CAMU	N

ON-SITE EQUIPMENT			
Equipment	Vendor / Tag No.	Work Performed	
CAT D400E Dump Truck (10)		CAMU	- - - -
JD D400 Dump Trucks (9)		Eastside	- - - -
CAT 324D long stick excavator		CAMU	- - - -
CAT D8R Dozer with disc		Eastside	- - - -
CAT 345 excavator, (3)		Eastside	- - - -
CAT 330 Excavator		Eastside	- - - -
Case double pan scrapers.		Eastside	- - - -
CAT D6 LGP Dozer (1)		Eastside	- - - -
Water Trucks (2)		Eastside	- - - -
637/631 Cat Scrapers (2)		CAMU	- - - -
CAT 16H Grader		CAMU	- - - -
CAT D-10 Dozer		CAMU	- - - -
CAT Water Trucks (2)		CAMU	- - - -
CAT D-6 Dozer, (2)		CAMU	- - - -
CAT 14H Grader		CAMU	- - - -
Gradall		CAMU	- - - -
JLG		CAMU	- - - -
IR Smooth drum Roller		CAMU, Phase 1	- - - -
Tenent Street Sweeper		Eastside and CAMU	- - - -
Bomag Smooth drum Roller		CAMU, Phase 1	- - - -
Chieftain 1400 Powerscreener		Eastside, screening 1" minus	- - - -

MATERIAL HANDLING (ON-SITE DELIVERY / REMOVAL)							
Material	Vendor	Today	UOM	Purpose	Delivery Verification		
					to date	Qty	Spec Tags
GCL	CETCO	0	rolls	For CAMU, On site		506	
Geocomposite	Agru	0	rolls	For CAMU, On site		599	
Geomembrane	Agru	0	rolls	For CAMU, On site		192	

WORK COMPLETED

Description of Work Executed Today

Eastside Mixing and Drying Activity:

- Day Shift:
 - Continued powerscreening material from (WST-8).
 - Watered PUC-3 & 4.
 - Worked on tarps and rails for haul trucks.
 - Finished deconing Case tractor and pans.
 - Prepared for night haul operations.
- Night Shift:
 - Continued hauling material from HP-3 stockpile to Phase I.
 - Continued hauling material from PUA-4 to Phase I.

CAMU Activity:

- Day Shift:
 - ESI continued installing GCL and geomembrane on North BMI Landfill.
 - Continued as-built survey of operation layer in Phase II.
 - Completed backfilling anchor trench for Phase II.
 - Continued grading North BMI Landfill.
 - Prepared for night haul operations.
- Night Shift:
 - Continue placing material from PUA-4 in Phase I.
 - Continue placing material from HP-3 in Phase I.

Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cumulative embankment placed: 0 cy
- Phase II embankment, complete.

Waste Placement

- Phase 1 estimated daily waste placed: 0 loads @ 20cy/load = 0 cy.
 night shift placed: 251 loads @ 18cy/load = 4,518 cy. (16 trucks).
- Phase 1 estimated cumulative waste placed: 223,570 cy. Western Ditch, NE Equilization, Eastside beta stockpile and PUA-4.PUB-3.
- Phase 1 Operations Layer placed, completed. Cumulative total: 21,662
- Phase 2 estimated night shift placed: 0 loads @ 18cy/load = 0 cy

Basic Remediation Company


875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	11-Dec-08	155

DAILY PHOTO LOG

Photo 1



CAMU: BMI North Landfill Cap liner installation continues.

Photo 2



CAMU: BMI North Landfill, view from the stockpile.

Photo 3



CAMU: Phase I and II from the stockpile

Photo 4



Eastside: PUA-4 dry pond.