Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011



DAILY PRODUCTION & QUALITY CONTROL REPORT Project No./Contract No. Project Title / Location Day of Report Report No. 6389 **BRC Eastside Common Areas Soils Remediation** 185 14-Jan-09

PROJECT POINTS OF CONTACT							
Position	Name	E-Mail Address	Phone No.				
BRC PROJECT MANAGER	Lee Farris	Ifarris@landwellco.com	702-567-0400				
BRC PROJECT MANAGER	Ranajit Sahu	sahuron@earthlink.net	702-567-0400				
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.c	970-260-5886				
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolution	720-641-8660				

Conditions		Tem	p (F)	Wind	Add'l Readings			
	DM .	0 101	Low	45		Precip. (In:Dy.)		
AM	Sunny/Clear	PM	Sunny/Clear	High	64	0mph	Humidity (%)	

Calm.

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager. CM	Construction Management Services.	N
Richard Davis	Project Engineer	Construction Management Services.	Y
Chris White	Assist. Const. Mgr	Construction Management Services.	Y
Wayne Hodgson	Assist. Const. Mgr	Construction Management Services.	Y
Kevin Cooke	Assist. Const. Mgr	Construction Management Services.	Y
June Laubinger	Admin Assistant	Construction Management Services.	Y
NAMES OF THE PARTY			

Name	Position	Trade / Work Performed	Y/N
Greg Corcoran	Design Engineer	Oversight	N
Dan Street	QA Manager	Oversight	Y
Jim Cox	QA/QC Supervisor	Oversight	N
Robecca Flynn	Engineer	Oversight	N
Wayne Wofford	QA/QC Tech	Oversight	N
Roland Derosier	QA/QC Tech	Oversight	Y
Camon Liddell	QA/QC Tech	Oversight	Y
Jeremy Osborn	QA/QC Tech	Oversight	Y
Victor Heredia	QA/QC Tech	Oversight	Υ
ON-SITE SUPPORT P	ERSONNEL	是1000mm 1000mm 10000mm 1000mm 1000mm 1000mm 1000mm 10000mm 1	
Name	Position	Trade / Work Performed	Y/N

Name	Position	Trade / Work Performed	Y/N	
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N	
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring,	Y	
Jerry Faucheux, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N	
				-
				i

OVERSITE PERSONNE	L	建	
Name	Position	Trade / Work Performed	Y/N
Mark Eizman, ASW	Inspector	Liner Inspector	Y
Devin Gordon, McGinley	Oversight	For NDEP	Y
Dock Kim, ATC	Field Observation	For AIG	Y
Joe Ludlow, ASW	Inspector	Liner Inspector	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
Brian Rakvica	Inspector	NDEP	N
PBS&J, Survey	Surveyors	Surveying, QA	N
ON-SITE CONTRACTOR	PERSONNEL		
		25 1 (34/ 1 5) /	Mai

Brian Hakvica	Inspector	INDEP	I IN I
PBS&J, Survey	Surveyors	Surveying, QA	N
ON-SITE CONTRACT	OR PERSONNEL		
Name	Company	Trade / Work Performed	Y/N
Erik Geringer	Entact	Project Manager	Y
Josh Carrol	Entact	Asst Project Manager	Y
Russ Karnes	Entact	Eastside, Superintendent	Y
Michael Carlson	Entact	Engineer	Y
Joe Curilla	Entact	Health & Safety Officer	Y
Timothy Stadt	Entact	Health and Safety Technician	Y
	Entact	26 Equipment Operators & Truck Drivers	Y
Ed Long	Entact	CAMU, Superintendent	Y
Lance Bruce	Entact	Health & Safety Officer	Y
Terry Harper	Entact	CAMU, Superintendent	Y
Rick McIntire	Entact	CSP, Safety	Y
Dale Walsh	Converse	CSP, Safety	Y

Ver 1.1 11/07 1 of 4

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	14-Jan-09	185
		14-3411-09	103

Entact	Asst Project Manager	Y
Environmental Specialties,Inc	1 Liner Superintendent	Y
Environmental Specialties,Inc	12 Laborers/ Seamers	Y
Kenney Survey	CAMU	N
ABC Survey	Eastside/CAMU, Mohawk Drive.	Y
	Environmental Specialties,Inc Environmental Specialties,Inc Kenney Survey	Environmental Specialties,Inc Environmental Specialties,Inc Environmental Specialties,Inc Kenney Survey CAMU

ON-SITE EQUIPMENT							
Equipment	Vendor / Tag No.		Work Performed				
CAT D400E Dump Truck (10)		CAMU		-	-	-	-
JD D400 Dump Trucks (9)		Eastside			-	-	
CAT 324D long stick excavator		CAMU		-	-	-	
CAT D8R Dozer with disc		Eastside			-	-	
CAT 345 excavator, (3)		Eastside			-	-	
CAT 330 Excavator		Eastside			-	-	
Case double pan scrapers.		Eastside, d	emobilized.		-	-	
CAT D6 LGP Dozer (1)		Eastside					
Water Trucks (2)		Eastside					
637/631 Cat Scrapers (2)		CAMU					
CAT 16H Grader		CAMU					
CAT D-10 Dozer		CAMU					
CAT Water Trucks (2)		CAMU					
CAT D-6 Dozer, (2)		CAMU					
CAT 14H Grader		CAMU					
Gradall		CAMU					
JLG		CAMU					
IR Smooth drum Roller		CAMU, Pha	ase 1				
Tenent Street Sweeper		Eastside ar	nd CAMU				
Bomag Smooth drum Roller		CAMU, Pha	ase 1				
Chieftain 1400 Powerscreener		CAMU, screening 1"& 6" minus					

	G (ON-SITE DELIVERY / REMOVA		HOH	Purpose	Delivery	Delivery Verification		
Material	Vendor	Today	UOM		to date Qty	Spec	Tags	
GCL	CETCO	0	rolls	For CAMU, On site	830			
Geocomposite	Agru	54	rolls	For CAMU, On site	832			
Geomembrane	Agru	0	rolls	For CAMU, On site	258			

WORK COMPLETED

Eastside Mixing and Drying Activity:

- <u>Day Shift:</u>
 Continued pushing up/stockpiling/drying material in SW Ponds.
- Continued pumping water from SW-7 to SW-12.
- Excavating in PUB-5 below the design grade. Inspected by Weston, inspector observed additional contamination. Entact directed to continue removing up to 18" of material. - Hauled dry material from PUB-5 to SW ponds for mixing.
- Night Shift:
- Continue hauling material from HP-3/HP-2 and PUC-4.

 Hauled operations layer material from WST-6/8.

CAMU Activity:

- Day Shift:
- ESI continued placing geosynthetics on N. BMI Landfill.
- Continued excavating contaminated soil from NW basin/Phase IIIB and placing in Phase I.
- Continued screening cover soils for N. BMI Landfill from 200,000 cy stockpile.

 Continued hauling/placing 1" and 6" minus cover soils on N. BMI Landfill.

 Continued grading in Phase IIIA.

- Continued scrape of Phase IIIB, IV, and V. and haul material to Phase II.
- Night Shift:
- Continue placing material in Phase II.

Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cummulative embankment placed: 0 cy
- Phase II embankment, complete.

- Phase 1 estimated daily waste placed, (Phase IIIB Trench): 100 loads @ 20 cy/load = 2,000 cy. (2 trucks).
- night shift placed: (0) loads @ 18cy/load = 0 cy.
 Phase 1 estimated cummulative waste placed: 292,160 cy.
- Phase 1 Operations Layer placed. completed. Cumulative total: 21,662
- Phase 2 estimated night shift placed: 294 loads @ 18cy/load = 5,292 cy, (19 trucks).

 Phase 2 estimated day shift placed: 26 loads @ 20 cy/load = 520 cy (Phase IV & V Scrape). (2 trucks).

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation		185
		14-Jan-09	103

- Phase 2 Operations Layer placed. daily: 0 cy. Cumulative total: 37,188 cy.

Phase 2 estimated cummulative waste placed: 80,966 cy

Geosynthetics. Estimated cummulative installed quantity by Phase.

- Phase 1 GCL placed:0 sf daily, 307,372 sf cummulative. - Phase 1 Geomembrane:0 sf daily, 307,372 sf cummulative

- Phase 1 Geocomposite: 0 sf daily, 3,372 sf cummulative.

- Phase 1 Geotextile: (0) sf daily. 69,340 sf cummulative.

-Phase 2 GCL placed: (0) sf daily, 498,468 sf cummulative.

-Phase 2 Geomenbrane: (0) sf daily, 498,468 sf cummulative. -Phase 2 Geocomposite: (0) sf daily, 520,592 sf cummulative.

HEALTH & SAFETY

Entact H&S Tailgates
Safety Topic: Eastside, Day: Discussed being aware of your surroundings and look out for one another.

Safety Topic: CAMU, Day: Discussed being aware of your surroundings and look out for one another.

Eastside and CAMU, Night: Discussed truckdriver communication with flaggers.

Safety Incidents: None.

Dust	Incidents:	None.

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

Daily CQA Summary.

Monitored waste placement from the eastside into Phase II. (Night Shift).

Monitored waste relocation from Phase IIIB to Phase I on the day shift.

Monitor surficial scrape at Phase IV and V and relocation of materials to Phase II.

Monitor the installation of geosynthetics at the N. BMI Landfill.

Monitor screening operations at the 200,000 cy stockpile.

Monitor the installation of cover soil at the N. BMI Landfill.

Monitor subgrade preparation at Phase IIIA.

Continue review of and updating of project documents and database to facilitate reporting.

ISSUES	AND/OR	ITEMS	OF DIS	cussi	ON
Discussion	of Issues /	Concerr	ns / Conv	ersations	/Top

ISITORS			
Name	Organization	Purpose of Visit	

Report Prepared By / Title

Signature

Richard Laubinger, Construction Manager

14-Jan-09

Ver 1.1 11/07 3 of 4

Basic Remediation Company 875 West Warm Springs Road Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	14-Jan-09	185
0	0	14-0411-09	


DAILY PHOTO LOG

Photo 1



Eastside: PUC-4 contamination in sidewall North.

Photo 2



CAMU: North BMI Landfill liner installation.

Photo 3



CAMU: North BMI Landfill liner installation.

Photo 4



CAMU: North BMI Landfill, Entact, Geosyntec, and Weston monitoring the placement of 1" minus 12" layer on liner.

4 of 4 Ver 1.1 11/07