Suite 810 143 Union Boulevard Lakewood, CO. 80228



DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
Task Order	(Name)	22 May 00	- 0
13520.003.001.0004	ENTACT, Soil Field Mixing Pilot Project	23-May-08	50

PROJECT POINTS OF	CONTACT		
Position	Name	E-Mail Address	Phone No.
PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.d	970-260-5886
Construction Manager	Richard Laubinger	Richard.Laubinger@westonsolutio	720-641-8660

WEATHER CONDITION	ONS			
	Conditions	Temp (F)	Wind	Add'l Readings
AM Cloudy	PM Light Rain	Low 52		Precip. (In/Dy.)
Aw Cloudy	Light Ham	High 73	Dir	Humidity (%)

Additional Weather Comments

Cloudy, light drizzle in AM. Cloudy, periods of rain in PM.

ON-SITE WESTON PERSONNEL					
Name	Position	Trade / Work Performed	Hrs	Signer	
Dick Laubinger	Construction Manager	Attended Safety Briefing.			
WIF I AND A		Observed load and haul material from SW-9 after lunch.			
		Daily Report	2.0		
		Observed PUE-1 soil remediation (6") cut, loading completion	2.0		
		Dust Control.	-		
		Total WESTON Man-Hours	4.0		

Name	Company	Trade / Work Performed	Hrs	Signe HASE
Eric Gehringer	Entact	Project Manager, Back on site.	10.0	
Russ Karnes	Entact	Superintendent/Safety., Off site home rotation	-	
Larry Haith	Entact	Water Truck Driver, Off Site home rotation.	-	
Terry Harper	Entact	Operator	10.0	
Michael Carlson	Entact	Engineer, Off Site, home rotation.	-	
Ubaldo Zubia	Entact	Operator,	10.0	
Leonel Mesa	Entact	Truck Driver.	10.0	
John Van Duren	Entact	Operator/Truck Driver, Off site, home rotation.	-	
Laurie Harper	Entact	Truck Driver	10.0	
James Stinnett	Entact	Operator/Truck Driver	10.0	
Josh Carrol	Entact	Project Controls, off site. Home rotation	-	
Devin Osborne	Entact	Operator/Truck Driver	10.0	
Mickey Lynch	Entact	Operator, New Employee	10.0	
			-	
			-	
			-	
		Total SUBCONTRACTOR Man-Hours	80.0	

Total Work-Hours on Site This Day

84.0

Cumulative Total Work-Hours From Previous Report TOTAL Work-Hours from Start of Construction

84.0

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location		Report No.
Task Order	(Name)	00 May 00	
13520.003.001.0004	ENTACT, Soil Field Mixing Pilot Project	23-May-08	50

ON-SITE EQUIPMENT								
Equipment	Vendor / Tag No	Vendor / Tag No. Work Performed		On-Site Hours				
Equipment	vendor/ rag ivo.	Work Fellornied	Used	Idle	Repair	Total		
CAT D400E Dump Truck (2)		No activity	-	-	-			
JD D400 Dump Trucks (3)		Two haul, PUE-1, haul SW-9 in PM.	30.0	-	-	30.0		
CAT 324D long stick excavator	- Wilder	PUE-1, remediating soils and loading trucks.	10.0	-	-	10.0		
CAT D8R Dozer with disc		Spread material at WST-3 and disking CTR1	10.0	-	-	10.0		
			-	-	-	•		
CAT 330 Excavator		Loading material from SW-9	10.0	-	-	10.0		
JD4206D Tractor & (2) Pans		No activity	-	-	-	-		
CAT D6 LGP Dozer, New on sit		Stockpiling at CTR-1	10.0°			10.0		
Water Trucks (2)		Dust control management	21.0			21.0		

MATERIAL HANDLING (ON	-SITE DELIVERY / REMOVAL)							
Material	Vendor	QTY	UOM	Purpose			/erificatio	
					Condtn	Qty	Spec	Tags
				177771111111111111111111111111111111111	++			
AFFALL							-	
		1						

WORK COMPLETED

Description of Work Executed Today

Safety Briefing.

After lunch loading material from SW-9, haul to WST-3.

D8 dozer disked CTR-1 area, then spreading material at WST-3...

Long stick excavator, remediating and loading dry soils at PUE-1, West Side of Mohawk Drive. Completed.

HEALTH & SAFETY

Description of Health & Safety Actions Taken Today / Safety Inspections Conducted

Site Safety Briefing, Topic: Fire Extinguishers and there usage..

QUALITY CONTROL

Description of Quality Control Actions Taken Today / Quality Inspections Conducted

Dust Control met requirements. Entact worked two water trucks, one dedicated to PUE-1 effort.

ISSUES AND/OR ITEMS OF DISCUSSION

Discussion of Issues / Concerns / Conversations / Topics

Ver 1.1 11/07 2 of 8

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
Task Order	(Name)	23-May-08	50
13520.003.001.0004	ENTACT, Soil Field Mixing Pilot Project	23-1VIAY-00	50

SITE VISITORS					
Name	Organization	Purpose of Visit	In	Out	Signed HASP
Linda Nations	BRC	Site inspection.			
<u> </u>		1			

Contractor Verification: On behalf of WESTON SOLUTIONS, INC., I certify this report is complete and correct, and all work performed and materials and equipment used during this reporting period are in compliance with the contract requirements, specifications, and standards, to the best of my knowledge, except as noted herein.

Report Prepared By / Title

Date Prepared

Signature

Dick Laubinger, Construction Manager

23-May-08

Ver 1.1 11/07 3 of 8

Weston Solutions, Inc

841 Bishop Street, Suite 2301 Honolulu, HI 96813

Phone: 808.275.2900 Fax: 808.585.7378



DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
Task Order	(Name)	00 May 00	50
13520.003.001.0004	ENTACT, Soil Field Mixing Pilot Project	23-May-08	50

DAIL V BHOTO LOC	
DAILY PHOTO LOG	
Photo 1	Photo 2
3.5-inch Width or 2.63-Inch Height	3.5-Inch Width or 2.63-Inch Height
Insert Picture Description	
Photos	Ph. 15 d
Photo 3	Photo 4
. 3.5-Inch Width or 2.63-Inch Height	. 3.5-Inch Width or 2.63-Inch Height .

Ver 1.1 11/07 4 of 8

Weston Solutions, Inc.

Suite 810 143 Union Boulevard Lakewood, CO 80228



CONSTRUCTION QUALITY CONTROL PREPARATORY INSPECTION Day of Report Project No./Contract No. Project Title / Location Inspection Time Task Order (Name) 13520.003.001.0004 ENTACT, Soil Field Mixing Pilot Project **DEFINABLE WORK ELEMENT** Code Criteria Work Description Spec Section **INSPECTOR** Signed Name Company Lic / Cert Signature HASP Υ PERSONNEL PRESENT [Crew Leaders for Work Element] Signed Name Organization Name Organization HASP HASP INSPECTION CHECKLIST YES NO* Place an "X" under YES or NO in response to the following 1. Review of Contract Requirements has been completed (SOW, Construction Documents, Code Criteria). Identified Х variances are noted. Verify that all materials and/or equipment has been submitted and approved, and if required, have been tested. Verify that provisions have been made to provide for required control inspection and testing. Work area has been examined to ensure that all required preliminary work has been completed and in compliance with the Contract Requirements. 5. Required materials, equipment, and sample work have been examined or inspected to ensure that they are on-hand, conform to approved shop drawings or submitted data, and are properly stored. Activity Hazard Analyses have been reviewed to ensure that safety requirements are met. Procedures for executing this work element, including elimination of repetitive deficiencies, have been discussed with applicable field crew(s) and subcontractors. 8. Construction tolerances and workmanship standards for the phase of work being inspected have been described and clearly conveyed. 9. Verify that the portion of the plan for the work to be performed has been accepted by the Contracting Officer or official representative. [And Client has been notified at least 48 hours in advance (or other notifications as may be required by contract) of beginning any of the required activities under this Feature of Work]. 10. The results of the Preparatory Phase Inspection (e.g., acceptable workmanship, actions required, etc.) are documented on this form, and additional sheets as necessary, and are attached to the Daily Production & Quality Control Report. * Explain any NO responses (attach additional sheets if necessary)

Ver 1.1 11/07 5 of 8

Weston Solutions, Inc

Suite 810 143 Union Boulevard Lakewood, CO 80228



CONSTRUCTION QUALITY CONTROL INITIAL / FOLLOW-UP INSPECTION

Project No./Contract No.	Pro	Day of Report	Day of Report Inspection Time				
Task Order		23-May-08	1500				
13520.003.001.0004	ENTACT, Soil Field Mixing Pilot Project				15	1500	
DEFINABLE WORK ELEME	ENT						
Work Description Spec Section			Code	Code Criteria			
							
INCREATOR							
INSPECTOR	Commonu	lie / Cont	Cinna			Signed	
Name	Company	Lic / Cert	Signa	lure		HASP	
			·				
PERSONNEL PRESENT [C	Crew Leaders for Work Element				•		
Name	Organization	Signed	Name	Organization		Signed	
· · · · · · · · · · · · · · · · · · ·		HASP		· · · · · · · · · · · · · · · · · · ·		HASP	
Name of the second seco				- A. C			
INSPECTION CHECKLIST							
Place an "X" under YES or NO in r					YES	NO*	
Preliminary work is in compliance with the Contract Requirements.					X		
2. Required control inspection and testing is in compliance with the Contract Requirements.						4.7784474	
 Workmanship standards established at the outset of this activity are acceptable and are in conformance with client and prime contractor expectations. 							
Workmanship and production rates are in conformance with the established standards.							
Any differences or conflicts in work scope or with contract specifications have been brought to the attention of the subcontractor and have been resolved.							
6. All activities are in compliance with the Safety Plan and applicable Activity Hazard Analyses.							
7. Client notified at least 48 hours in advance of beginning the initial phase of work for this Feature of Work.							
The Initial or Follow-Up Meeting has been conducted by the Project QA/QC Lead and was attended by the appropriate site personnel and the work leaders responsible for this Feature of Work.							
Initial Phase Inspection has been repeated for each new crew to work on-site or at any time specified quality standards are not being met							
10. The results of the Initial or Follow-Up Phase Inspection (e.g., acceptable workmanship, actions required, etc.) are documented on this form, and additional sheets as necessary, and are attached to the Daily Production & Quality Contro Report.							

* Explain any NO responses (attach additional sheets if necessary)

Ver 1.1 11/07 6 of 8

Weston Solutions, Inc Suite 810 143 Union Boulevard Lakewood, CO 80228



DAILY FIELD TAILGATE SAFETY MEETING REPORT										
Project No./Contract No.	Project Title / Location				Day of R		f Report			
Task Order	(Name)				Success Success	decy	00.1	1011 00		
13520.003.001.0004	ENTACT, So	oil Field Mixing	Pilot Pi	roject					23-14	1ay-08
EMERGENCY LOCATIONS										
Name	Addr	ress			F	hone N	о.	Ne	earest Pl	none
THE PART OF THE PA								72	20-641-8	3660
	·						<u>·</u>			
WORK ACTIVITIES (THIS SH	IIFT)									
Refer to Health & Safety Plan / Act	ivities Hazard Analysis									
Act. No.	Task Description		HASP Page	Chem	Level Phys	Level	PPE Requ Mo	dification		Topic Covered
	_/									
- 1-0 1AMA		,								
						l				
ADDITIONAL SITE HAZAR	DS									
	Safety Plan / Activities Hazard Ana	alysis								
HAZARDS (CHEMICAL / PI		Γ								Topic
Description of Potei	ntial Hazards / Risks	Sate	ty Proce	edures &	Special E	-quipme	nt/Techniq	res		Covered
	N-94444L				····					
	- To Flad Million I									
DISCUSSION TOPICS										
AHA Potential Hazards and Control	N Magazines Discussed Today									
Daily Work Scope & Activity Ha										
Bany Work Ocope a Activity The	3221 G 5									
	•								•	
Additional Safety Topics Discussed	d Today				•					
·	•			-						
Additional Comments / Special To	oics (Incidents, Actions Taken, Item	ns of Concerns, Et	c.) Discu	issed Too	day					

Ver 1.1 11/07 7 of 8

DAILY FIELD TAILGATE SAFETY MEETING REPORT

Project No./Contract No.	Project Title / Location	THUIDE BASEO	Day of Report
Task Order	(Name)	Success III	23-Mav-08
13520.003.001.0004	ENTACT, Soil Field Mixing Pilot Project	A. S. C.	23-141ay-06

TAILGATE SAFETY MEETING ATTENDE	ES	
Print Name	Organization	Sign Name
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
1004 807 8404 1		
	Workers .	
7.44.64.64.64.64.66.66.66.66.66.66.66.66.	1 CONTRACTOR OF THE CONTRACTOR	
,		
	·	·

Meeting Conducted By	Phone	Signature	Start Time	Completed