

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	14-Jul-08	21

Position	Name	E-Mail Address	Phone No.
BRC PROJECT MANAGER	Lee Farris	<a href="mailto:lfarris@landwellco.com">lfarris@landwellco.com</a>	702-567-0400
BRC PROJECT MANAGER	Ranajit Sahu	<a href="mailto:sahuron@earthlink.net">sahuron@earthlink.net</a>	702-567-0400
CONST. PROJECT MANAGER	Dan Brennecke	<a href="mailto:Dan.Brennecke@westonsolutions.com">Dan.Brennecke@westonsolutions.com</a>	970-260-5886
Construction Manager	Richard Laubinger	<a href="mailto:Richard.Laubinger@westonsolutions.com">Richard.Laubinger@westonsolutions.com</a>	720-641-8680

Conditions				Temp (F)	Wind	Add'l Readings	
AM	Cloudy	PM	Light Rain	Low 83		Precip. (in/Dy.)	
				High 98	Dir	Humidity (%)	

**Rain overnight Sunday, Morning: Cloudy, Afternoon: brief period of light Rain, wind and lightning.**

Name	Position	Trade / Work Performed	Y/N
Dick Laubinger	Construction Manager	Construction Management Services.	Y
Dan Brennecke	Project Manager. CM	Construction Management Services.	N
	Project Engineer	Construction Management Services.	N
	Admin Assistant	Construction Management Services.	N

[illegible]

Name	Position	Trade / Work Performed	Y/N	
		Air Monitoring	Y	

[illegible]

## DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	14-Jul-08	21

## ON-SITE EQUIPMENT

[illegible]

**MATERIAL HANDLING (ON-SITE DELIVERY / REMOVAL)**

[illegible]

## WORK COMPLETED

Description of Work Executed Today

Eastside Mixing and Drying Activity:

- SW-9 Loading out wet soils on (3) trucks, hauling to WST-3. D6 dozer spreading out wet material.
- D8 dozer diskimg all areas.
- D6 dozer grading haul roads to AST fuel tank.
- CAT 330, excavator, cutting in ramps to SC1 and SW-4.
- Motorgrader grading haul roads.
- Estimated dried material hauled to stockpile: (TBD) cy daily, (TBD)cy cumulative.

**CAMU Activity:**

Excavation	
------------	--

- Phase 1, Rough cutting slopes, and floor with 6 Scrapers and hauling material to north stockpile.
- Excavating Northwest Retention Pond. (8,400) cy daily, (TBD) cumulative.

<b>Embankment</b>	
-------------------	--

- Phase 1 estimated daily embankment placed: 0 cy  
- Phase 1 estimated cumulative embankment placed: 0 cy

Waste Placement	
-----------------	--

- Phase 1 estimated daily waste placed: 0 cy
- Phase 1 estimated cumulative waste placed: 0 cy

## Geosynthetics

- Phase 1 GCL placed: 0 sf daily, 0 sf cumulative
- Phase 1 Geomembrane: 0 sf daily, 0 sf cumulative
- Phase 1 Geocomposite: 0 sf daily, 0 sf cumulative
- Phase 1 Geotextile: 0 sf daily, 0 sf cumulative

## Other \_\_\_\_\_

### Perimeter Fence Inspection and Repair

7/12/08 One section of fence forced down East of the Main entrance.

## DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	14-Jul-08	21

### HEALTH & SAFETY

*Description of Health & Safety Actions Taken Today / Safety Inspections Conducted*

#### Entact H&S Tailgates

Morning: Slippery Conditions.

Afternoon: DECON PPE will be staged near the decon area, discussion.

#### American Asphalt Tailgates

Morning: Slope Safety.

### QUALITY CONTROL

*Description of Quality Control Actions Taken Today / Quality Inspections Conducted*

#### Daily CQA Summary

Geomembrane delivery monitored roll numbers verified

#### Deviations from CQA Plan

None

### ISSUES AND/OR ITEMS OF DISCUSSION

*Discussion of Issues / Concerns / Conversations / Topics*

Shutdown one half hour for lightning.

### SITE VISITORS

Name	Organization	Purpose of Visit			
Lee Farris	BRC	Site Visit.			
Mark Paris	BRC	Site Visit.			
Linda Nations	BRC	Site Visit.			

Report Prepared By / Title

Dick Laubinger, Construction Manager

Date Prepared

14-Jul-08

Signature

**Weston Solutions, Inc**

841 Bishop Street, Suite 2301

Honolulu, HI 96813

Phone: 808.275.2900

Fax: 808.585.7378

**DAILY PRODUCTION & QUALITY CONTROL REPORT**

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
<b>6389</b> 0	<b>BRC Eastside Common Areas Soils Remediation</b> 0	14-Jul-08	21

**DAILY PHOTO LOG**

Photo 1

3.5-Inch Width or 2.63-Inch Height

Insert Picture Description

Photo 2

3.5-Inch Width or 2.63-Inch Height

Photo 3

3.5-Inch Width or 2.63-Inch Height

Photo 4

3.5-Inch Width or 2.63-Inch Height