

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	13-Oct-09	454

- Western Hook, continued loading out OTR trucks, hauling material to CAMU for placement.
 - Galleria Scrape, plumbed water connection for stand tank. PBS&J completed survey layout.

- Night Shift:
 - Hauled material from WST-4, WST-5 and Beta Ditch stockpiles.

CAMU Activity:

- Day Shift
 - Placed material from Western Hook and Eastside into Phase II and Phase IIIB.
 - Phase IIIA, ESI began deploying GCL and Geomembrane liner at east end, first tier.
 - Phase IIIA, continued finish grading on slopes.
 - Phase II, grading waste.

- Night Shift:
 - Placed material from eastside in CAMU, Phase IIIB and Phase IV.

Embankment
 - Phase I embankment, complete.
 - Phase I estimated cumulative embankment placed:
 - Phase II embankment, complete.

Sump/Vadose Monitoring:

Phase I: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase II: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase IIIB: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
 Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Inspections: CAMU: NA.
 Eastside: Inspected perimeter fence, All Secure.

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

Phase I	Previous Daily Cumulative =	315,300	cy
	Operations layer placed (completed) for liner certification. =	21,662	0
	Daily Day shift waste placed today: (0) loads @ 20 cy/load (0 trucks) =	0	cy
	Daily Night shift placed today: (0) loads @ 18cy/load (0) trucks =	0	cy
	To Date Phase I estimated cumulative waste placed =	315,300	cy
Phase II	Previous Daily Cumulative =	1,033,462	cy
	Operations layer placed (completed) for liner certification. =	37,188	0
	Daily Day shift waste placed today: Western Hook, (0) loads @ 18 cy/load (0) trucks =	0	cy
	Daily Day shift waste placed today: Eastside Waste, (0) loads @ 18cy/load (0) trucks =	0	cy
	Daily Night shift placed today: (0) loads @ 18cy/load (0) trucks =	0	cy
	To Date Phase II estimated cumulative waste placed =	1,033,462	cy
Phase IIIA	Previous Daily Cumulative =	222,174	cy
	Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks =	0	cy
	Operations layer placed (completed for liner certification = 21,276)	21,276	0
	Daily Day shift waste placed today: (0) loads @ 18 cy/load (0) trucks =	0	cy
	Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =	0	cy
	To Date Phase IIIA estimated cumulative waste placed =	222,174	cy
Phase IIIB	Previous Daily Cumulative =	254,418	cy
	Operations layer placed (completed) for liner certification. =	21,978	0
	Daily Day shift waste placed from: Eastside/Western Hook (18) loads @ 18 cy/ld (16) trucks =	3,402	cy
	Daily Night shift waste placed today: (167) loads @ 18cy/load (16) trucks =	3,008	cy
	To Date Phase IIIB estimated cumulative waste placed =	260,826	cy
Phase IV	Previous Daily Cumulative =	130,734	cy
	Operations layer placed (completed) for liner certification =	37,314	0
	Daily Day shift waste placed today: (0) loads @ 18 cy/load (0) trucks =	0	cy
	Daily Night shift waste placed today: (217) loads @ 18cy/load (18) trucks =	3,906	cy
	To Date Phase IV estimated cumulative waste placed =	134,640	cy
Phase V	Previous Daily Cumulative =	49,266	cy
	Operations layer placed (completed) for liner certification =	40,284	0
	Daily Day shift waste placed today: From: (0) loads @ 18 cy/load (0) trucks =	0	cy
	Daily Night shift waste placed today: (0) loads @ 18cy/load (0) trucks =	0	cy
	To Date Phase V estimated cumulative waste placed =	49,266	cy

Cumulative Total To Date All Phases =	2,015,668	cy
Estimated Waste at Completion (cy)	2,400,000	% Complete
		84.0%

Geosynthetics Placed

Phase (complete)	Previous	Placed	Cumulative Placed
Phase I (complete)			
GCL	307,372	0	307,372
Geomembrane	307,372	0	307,372
Geocomposite	307,372	0	307,372
Geotextile	69,340	0	69,340
Phase II (complete)			
GCL	498,468	0	498,468
Geomembrane	498,468	0	498,468
Geocomposite	520,592	0	520,592
Geotextile	0	0	0
Phase IIIA			
GCL	221,000	0	221,000
Geomembrane	221,000	0	221,000
Geocomposite	221,000	0	221,000
Geotextile	20,000	0	20,000
Phase IIIB			
GCL	340,535	0	340,535
Geomembrane	340,535	0	340,535
Geocomposite	340,535	0	340,535
Geotextile	50,000	0	50,000
Phase IV			
GCL	459,942	0	459,942
Geomembrane	459,942	0	459,942
Geocomposite	459,952	0	459,952
Geotextile	12,390	0	12,390
Phase V			
GCL	558,653	0	558,653
Geomembrane	558,653	0	558,653
Geocomposite	558,653	0	558,653
Geotextile	15,925	0	15,925

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	13-Oct-09	454

DAILY PHOTO LOG

Photo 1



CAMU: Phase IIIB.

Photo 2



CAMU: Phase IIIA.

Photo 3



CAMU: Phase IIIA.

Photo 4



CAMU: Phase IIIA.