

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	19-Jan-10	546

Position	Name	E-Mail Address	Phone No.
BRC PROJECT MANAGER	Lee Farris	lfarris@landwellco.com	702-567-0400
BRC PROJECT MANAGER	Ranjati Sahu	sahuranj@earthlink.net	702-567-0400
CONST. PROJECT MANAGER	Dan Brennecke	Dan.Brennecke@westonsolutions.com	970-260-5886
Construction Manager	Richard I. Aubinger	Richard.I.aubinger@westonsolution.com	770-641-8660

Conditions				Temp (°F)	Wind	Add'l Readings	
AM	Light Rain	PM	Rain	Low 41		Precip. (in/hr)	0.54
				High 56	SE 10mph	Humidity (%)	0

Additional Weather Comments

Night Shift, canceled due to weather.

[illegible]

Name		Position	Trade / Work Performed	Y/N
Greg Corcoran		Design Engineer	Oversight	N
Dan Street		QA Manager	Oversight	N
Jim Cox		QA/QC Supervisor	Oversight	Y
Rebecca Flynn		Engineer	Oversight	N
Camron Littlefield		QA/QC Tech	Oversight	Y
Giorgio Malina		QA/QC Tech	Oversight	N
Victor Heredia		QA/QC Tech	Oversight	Y
John Duncan		QA/QC Tech	Oversight	Y

Name	Position	Trade / Work Performed	Y/N	
Doug Herlocker, Tetra Tech	Air Monitoring Specialist	Air Monitoring	N	
Becky Dano, Tetra Tech	Air Monitoring Specialist	Air Monitoring	Y	

Name	Position	Trade / Work Performed	Y/N
Bob Meyer, ASW	Inspector	Liner Inspector,	Y
Devin Gordon, MGA	Oversight	For NDEP	Y
Brian Rakivca	Inspector	NDEP	N
Steve Morrow, ASW	Inspector	Liner Inspector	N
PBS&J, Survey	Surveyors	Survey	N

[illegible][illegible]

Material	Vendor	Today	UOM	Purpose	Delivery Verification		
					to date	Qty	Spec
GCL	CETCO	0	rolls	For CAMU, On site		2271	
Geocomposite	Agru	0	rolls	For CAMU, On site		2442	
Geomembrane	Agru	0	rolls	For CAMU, On site		558	

Eastside Mixing and Draying Activity:

- Day Shift:

- Continued working on final scrape in Beach, SW, HP and CTR ponds. Hauling material to Beach Ditch stockpile.
- Over the road trucks hauling soils from HP ponds to CAMU, Phase 5. Shut down hauling at approx. 3 pm due to inclement weather.
- Over the road trucks hauling soils from Galleria Parcel 2 to CAMU, Phase 5. Shut down hauling at approx. 3 pm due to inclement weather.

- Night Shift:

- No activities due to inclement weather.

DAILY PRODUCTION & QUALITY CONTROL REPORT			
Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389	BRC Eastside Common Areas Soils Remediation	19-Jan-10	546
<div><div>CAMU Activity:</div><div><div>- Day Shift</div><div>- Continued placing material from Eastside and Galleria in Phase V.</div><div>- Continued placing interim cover on Phase IIIB and Phase IV.</div><div>- Continued crushing rock for gravel mulch.</div><div>- Graded waste in Phase IV and Phase V.</div><div>- ESI liner crew continued installing geosynthetics on Phase I and Phase II.</div><div>- Continued placing 1' minus final cover on geosynthetics at Phase I and Phase II.</div></div><div><div>- Night Shift</div><div>- No activities, due to inclement weather.</div></div><div><div>Embankment</div><div>- Phase I embankment, complete.</div><div>- Phase 1 estimated cumulative embankment placed:</div><div>- Phase II embankment , complete.</div></div><div><div>Sump/Vadose Monitoring:</div><div>Phase I: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).</div><div>Vadose: Measurement taken: (N/A) Water Pumped: (N/A).</div><div>Phase II: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).</div><div>Vadose: Measurement taken: (N/A) Water pumped: (N/A).</div><div>Phase IIIB: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).</div><div>Vadose: Measurement taken: (N/A) Water Pumped: (N/A).</div><div>Phase V: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).</div><div>Vadose: Measurement taken: (N/A) Water pumped: (N/A).</div></div><div><div>Inspections:</div><div>CAMU: N/A.</div></div><div>Fastlane: Performed fence line inspection on waste/soil perimeter. All secure.</div></div>			

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

Phase I	
Previous Daily Cumulative =	372,886 cy
Operations layer placed (completed) for liner certification. = 21,662	0 cy
Daily Day shift waste placed today: Galleria/Eastside, (0) loads @ 17 cy/load (0) trucks =	cy
Daily Night shift placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase I estimated cumulative waste placed =	372,886 cy
Phase II	
Previous Daily Cumulative =	1,072,405 cy
Operations layer placed (completed) for liner certification. = 37,188	cy
Daily Day shift waste placed today: Galleria Scrape, (0) loads @ 17 cy/load (0) trucks =	cy
Daily Day shift waste placed today: Eastside Waste, (0) loads @ 17cy/load (0) trucks =	cy
Daily Night shift placed today: (0) loads @ 21 cy/load (0) trucks =	cy
To Date Phase II estimated cumulative waste placed =	1,072,405 cy
Phase IIIA	
Previous Daily Cumulative =	222,174 cy
Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks =	cy
Operations layer placed (completed for liner certification = 21,276)	cy
Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks =	cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase IIIA estimated cumulative waste placed =	222,174 cy
Phase IIIB	
Previous Daily Cumulative =	439,547 cy
Operations layer placed (completed) for liner certification. = 21,978	cy
Daily Day shift waste placed from: Galleria/Eastside (0) loads @ 17 cy/l'd (0) trucks =	cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase IIIB estimated cumulative waste placed =	439,547 cy
Phase IV	
Previous Daily Cumulative =	434,225 cy
Operations layer placed (completed) for liner certification = 37,314	cy
Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks =	cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase IV estimated cumulative waste placed =	434,225 cy
Phase V	
Previous Daily Cumulative =	344,129 cy
Operations layer placed (completed) for liner certification = 40,284	cy
Daily Day shift waste placed from: Eastside and Galleria (95) loads @ 17 cy/load (8) trucks =	1,615 cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks =	cy
To Date Phase V estimated cumulative waste placed =	345,744 cy
11/01/09 Volume Adjustment to Correlate with CAMU Placement Survey	123,750 cy

Cumulative Total To Date All Phases =	Estimated Waste at Completion (cy)	% Complete
	3,010,731 cy	103.8%
	2,900,000	

Geosynthetics Placed

	Previous	Placed	Cumulative Placed
Phase I (complete)			
GCL	307,372	0	307,372
Geomembrane	307,372	0	307,372
Geocomposite	307,372	0	307,372
Geotextile	69,340	0	69,340
Phase II (complete)			
GCL	498,468	0	498,468
Geomembrane	498,468	0	498,468
Geocomposite	520,592	0	520,592
Geotextile	0	0	0
Phase IIIA			
GCL	221,000	0	221,000
Geomembrane	221,000	0	221,000
Geocomposite	221,000	0	221,000
Geotextile	20,000	0	20,000
Phase IIIB			
GCL	340,535	0	340,535
Geomembrane	340,535	0	340,535
Geocomposite	340,535	0	340,535
Geotextile	50,000	0	50,000
Phase IV			
GCL	459,942	0	459,942
Geomembrane	459,942	0	459,942
Geocomposite	459,952	0	459,952
Geotextile	12,390	0	12,390
Phase V			
GCL	558,653	0	558,653

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

Project No./Contract No.	Project Title / Location	Day of Report	Report No.
6389 0	BRC Eastside Common Areas Soils Remediation 0	19-Jan-10	546

DAILY PHOTO LOG

Photo 1



CAMU: Phase I and Phase II.

Photo 2



CAMU: Phase II, east slope.

Photo 3



CAMU: Phase I and Phase II.

Photo 4



Eastside: HP Pond.