
Basic Remediation Company


Restoration Advisory Committee Meeting

Dr. Ranajit (Ron) Sahu Project Manager January 7, 2010


Topics


- Introductions and Approval of Minutes (Transcript)
- Remediation Update
- Other Work Update
- Planned Activities
- Next Meeting To be discussed





CAMU Phases








Remediation Update

- Air Monitoring Continues
 - Phase IIA in progress (2 monitors in Eastside, 2 in CAMU) through Eastside mass remediation completion
 - All other Air Monitoring Reports (Phases IIIA, IIIB, IIIC) approved by the NDEP
- CAMU Status
 - In Progress [Waste Placed in CAMU ~ 2.9 mm cu. yds.]
 - CAMU Phase I Cap in progress
 - CAMU Phase II Cap in progress
 - CAMU Phase IIIA Cap in progress
 - CAMU Phase IIIB Cap in progress
 - CAMU Phase IV Waste placement/cap in rogress
 - CAMU Phase V Waste placement

Remediation Update (contd.)

- CAMU Status (contd.)
 - BMI Landfill North Cover placed
 - BMI Landfill South Cover placed
 - N-E Detention Basin completed
 - N-W Detention Basin completed
 - Slit Trenches completed
- Eastside
 - TIMET Ponds Sub-area Excavation continuing
 - Staging Sub-area Excavation continuing



Other Work Update

<u>Sub-Areas Status</u>						
Sub-Area Name	Acres	Samples	Locations	ConfSAP	C-Samp	NFA
Parcel 4A	243.7			Арр	Done	Done
Parcel 4B	278.4			Арр	Done	Done
Utility Corridor	8.4	60	46	Арр	Done	Done
Mohawk	54.74	98	38	Арр	Done	RA Revision
Western Hook	226.95	279	129	Арр	R1/R2/R3 (Lab)	Prelim
Southern RIBs	95.83	154	63	Арр	R1/R2/R3/R4 (Lab)	Prelim
Galleria North	144.25	212	96	Арр	R1/R2	Prelim
SN Commercial	44.33	103	50	Арр	R1/R2 (Lab)	Prelim
First Eight Rows-Phase II (7B)	126.48	240	108	Арр	R1	TBD
Open Space	151.33	336	151	Арр	R1	Prelim
Upper Ponds	283.3	407	183	Арр	R1 (Lab)	Prelim
First Eight Rows-Phase I (7A)	77.23	140	63	Арр	R1	Prelim
TIMET Ponds	209.89	391	176	In Review	R1 in 2/10	TBD
Spray Wheel	128.71	180	81	Арр	R1 in 1/10	TBD
Staging	114.97	262	118	2/15/10	R1 in 4/10	TBD
TIMET Ponds Spray Wheel	209.89 128.71	391 180	176 81	In Review App	R1 in 2/10 R1 in 1/10	TE TE

Other Work Update (contd.)

Background Reports

- Suppl. Shallow Soils : Approved
- Deep Soils : Approved
- Integrated Background Report : In preparation

Groundwater

- Eastside 2009 groundwater sampling
 - Completed. One well being repaired/resampled.
- Modeling in progress
 - Calibration Report accepted
 - Solute transport modeling work plan approved. Modeling in progress.
- CAMU area baseline groundwater monitoring [4 Qtrs. in 2009]
 - Q1/Q2/Q3/Q4 Sampling Completed
 - Q1/Q2/Q3 DVSR Approved. Q4 DVSR in preparation
 - Q4/Annual Sampling Report in preparation

2010 Q1 Next Steps

- Remediation // Related Activities Continue
- Soils Closure // Related Activities
 - Create Final Background Datasets Report
 - Western Hook / Open Space Arsenic Background
 - Obtain NFA Mohawk, SRIBS, Sunset North
 - Rescrape Open Space, Upper Ponds, First Eight Rows
 - Confirmation SAPs Obtain approval TIMET
 - Confirmation SAPs Create for Staging sub-areas
 - Add. Field Sampling Flux/Soil Gas; Indoor/GW Radon

2009 Q4 Planned Activities

Groundwater

- Complete Eastside Groundwater Modeling
- Await NDEP comments on Upgradient and Isotope/Connectivity Reports
- Submit WHook/Open Space arsenic report
- Update Eastside CSM
- Complete 2009 CAMU Groundwater Monitoring Report
- Develop supplemental CAMU monitoring program
- Develop Long-Term CAMU GW Monitoring Program

Public Involvement

- Public Involvement Activities
 - Website at <u>www.landwellco.com</u> updated
 - All important project documents available on the website
 - Construction updates added