

| Project No./Contract No. | Project Title / Location | Day of Report | Report No. |
|--------------------------|---|---------------|------------|
| 6389 | BRC Eastside Common Areas Soils Remediation | 01-Feb-10 | 559 |
| | | | |

| Position | Name | E-Mail Address | Phone No. |
|------------------------|---------------------|--|--------------|
| BRC PROJECT MANAGER | Lee Farris | lfarris@landwellco.com | 702-567-0400 |
| BRC PROJECT MANAGER | Ranjati Sahu | sahuranj@earthlink.net | 702-567-0400 |
| CONST. PROJECT MANAGER | Dan Brennecke | Dan.Brennecke@westonsolutions.com | 970-260-5886 |
| Construction Manager | Richard I. Aubinger | Richard.I.aubinger@westonsolution.com | 770-641-8660 |

| Conditions | | | | Temp (°F) | | Wind | | Add'l Readings | |
|------------|----------------------|----|----------------------|-----------|----|------|------|-----------------|---|
| AM | Sunny / Party Cloudy | PM | Sunny / Party Cloudy | Low | 37 | | | Precip. (in/Dy) | 0 |
| | | | | High | 58 | NE | 5mph | Humidity (%) | 0 |

[illegible]

| Name | | Position | Trade / Work Performed | Y/N |
|-------------------|------------------|-----------|------------------------|-----|
| Greg Corcoran | Design Engineer | Oversight | | N |
| Dan Street | QA Manager | Oversight | | N |
| Jim Cox | QA/QC Supervisor | Oversight | | Y |
| Rebecca Flynn | Engineer | Oversight | | N |
| Samon Littlefield | QA/QC Tech | Oversight | | Y |
| Graciano Malina | QA/QC Tech | Oversight | | Y |
| Victor Heredia | QA/QC Tech | Oversight | | Y |
| John Duncan | QA/QC Tech | Oversight | | Y |

[illegible]

| Name | Position | Trade / Work Performed | Y/N |
|-------------------|-----------|------------------------|-----|
| Bob Meyer, ASW | Inspector | Liner Inspector, | Y |
| Devin Gordon, MGA | Oversight | For NDEP | Y |
| Brian Rakivica | Inspector | NDEP | N |
| Steve Morrow, ASW | Inspector | Liner Inspector | N |
| PBS&J, Survey | Surveyors | Survey | N |

| Name | Company | Trade / Work Performed | Y/N |
|----------------------|---------------------------------|--|-----|
| Erik Gehring | Contact | Project Manager | N |
| El Blackburn | Contact | Asst Project Manager | Y |
| Josh Carroll | Contact | Asst Project Manager, Eastside Manager | Y |
| Michael Carlson | Contact | Engineer | Y |
| Joe Curllis Day | Contact | Health & Safety Officer | Y |
| Timothy Stadl Day | Contact | Health and Safety Officer | N |
| Roger Wagner, Night | Contact | Eastside, Superintendent | N |
| Russell Karnes | Contact | CAMU, Superintendent, Western Hook. | Y |
| Lance Bruce, Night | Contact | Health & Safety Officer | Y |
| Terry Harper, Night | Contact | CAMU, Superintendent | Y |
| Rick McIntire | Contact | CSP, Health & Safety | Y |
| Scott Zattau, Day | Contact | Health & Safety Officer | N |
| Jose Martinez, Night | Contact | Health & Safety Officer | Y |
| Dawn Breedlove | Contact | Health & Safety Technician | Y |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | Environmental Specialties, Inc. | Liner Crew. (1) Supt., (10) Laborers/ Seamens mobilized. | N |
| | ABC Survey | Eastside/CAMU/Western Hook | N |

[illegible]

| Material | Vendor | Today | UOM | Purpose | Delivery Verification | | |
|--------------|--------|-------|-------|-------------------|-----------------------|------|------|
| | | | | | to date | Qty | Spec |
| GCL | CETCO | 0 | rolls | For CAMU, On site | | 2271 | |
| Geocomposite | Agru | 0 | rolls | For CAMU, On site | | 2442 | |
| Geomembrane | Agru | 0 | rolls | For CAMU, On site | | 558 | |

Eastside Mixing and Drving Activity:

Day Shift:

- Continued final scrape at fuel tank rd, SW Pond, and south of HP-3 areas.
- Day hauling continued from Beta Ditch stockpile to CAMU for placement.

Night Shift:

- Hauled material from Beta Ditch stockpiles.

| DAILY PRODUCTION & QUALITY CONTROL REPORT | | | |
|---|---|---------------|------------|
| Project No./Contract No. | Project Title / Location | Day of Report | Report No. |
| 6389 | BRC Eastside Common Areas Soils Remediation | 01-Feb-10 | 559 |

CAMU Activity:

- Day Shift

- Continued power screening 1" and 6" minus soil at 200,000 cy stockpile.
- Uncovered toe of slope at anchor trench for liner tie in on Phase I, Phase II and Phase IIIB.
- Continued to place 1" and 6" final cover soils on Phase I, Phase II and Phase IIIB.
- Placing material from eastside in Phase V.
- ESI liner crew, continued installing geosynthetics on Phase I, Phase II and Phase IIIB.
- Entact continued to monitor Phase V sump.

- Night Shift

- Placed material in Phase IV and Phase V.

Embankment

- Phase 1 embankment, complete.
- Phase 1 estimated cumulative embankment placed:
- Phase II embankment, complete.

Sump/Vadose Monitoring:

Phase I: LCRS Sump: Measurement taken: (1,300) Water Pumped: (N/A).
Vadose: Measurement taken: (0.563) Water Pumped: (N/A).

Phase II: LCRS Sump: Measurement taken: (2,550) Water Pumped: (N/A).
Vadose: Measurement taken: (N/A) Water pumped: (N/A).

Phase IIIB: LCRS Sump: Measurement taken: (N/A) Water Pumped: (N/A).
Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Phase V: LCRS Sump: Measurement taken: (2,842) Water pumped: (3,510 gal).
Vadose: Measurement taken: (N/A) Water Pumped: (N/A).

Inspections: CAMU:

Eastside: Inspected fence perimeter: All secure.

Estimated Waste Placement (Estimated volumes do not account for shrinkage due to loss of moisture on wet ponds)

Phase I

Previous Daily Cumulative = 372,886 cy
Operations layer placed (completed) for liner certification. = 21,662 0 cy

Daily Day shift waste placed today: Galleria/Eastside, (0) loads @ 17 cy/load (0) trucks = cy
Daily Night shift placed today: (0) loads @ 21cy/load (0) trucks = cy

To Date Phase I estimated cumulative waste placed = 372,886 cy

Phase II

Previous Daily Cumulative = 1,072,405 cy
Operations layer placed (completed) for liner certification. = 37,188 cy

Daily Day shift waste placed today: Galleria Scrape, (0) loads @ 17 cy/load (0) trucks = cy
Daily Day shift waste placed today: Eastside Waste, (0) loads @ 17cy/load (0) trucks = cy
Daily Night shift placed today: (0) loads @ 21 cy/load (0) trucks = cy

To Date Phase II estimated cumulative waste placed = 1,072,405 cy

Phase IIIA

Previous Daily Cumulative = 222,174 cy
Operations layer placed directly in Phase IIIA today: (0) loads @ 18 cy/load (0) trucks = cy

Operations layer placed (completed for liner certification = 21,276) cy
Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks = cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks = cy

To Date Phase IIIA estimated cumulative waste placed = 222,174 cy

Phase IIIB

Previous Daily Cumulative = 439,547 cy
Operations layer placed (completed) for liner certification. = 21,978 cy

Daily Day shift waste placed from: Galleria/Eastside (0) loads @ 17 cy/d (0) trucks = cy
Daily Night shift waste placed today: (0) loads @ 21cy/load (0) trucks = cy

To Date Phase IIIB estimated cumulative waste placed = 439,547 cy

Phase IV

Previous Daily Cumulative = 440,651 cy
Operations layer placed (completed) for liner certification = 37,314 cy

Daily Day shift waste placed today: (0) loads @ 17 cy/load (0) trucks = cy
Daily Night shift waste placed today: (179) loads @ 21cy/load (13) trucks = 3,759 cy

To Date Phase IV estimated cumulative waste placed = 444,410 cy

Phase V

Previous Daily Cumulative = 404,178 cy
Operations layer placed (completed) for liner certification = 40,284 cy

Daily Day shift waste placed from: Eastside, (162) loads @ 17 cy/load (10) trucks = 2,754 cy
Daily Night shift waste placed today: (196) loads @ 21cy/load (15) trucks = 4,116 cy

To Date Phase V estimated cumulative waste placed = 411,048 cy

11/01/09 Volume Adjustment to Correlate with CAMU Placement Survey 123,750 cy
12/31/09 Volume Adjustment to Correlate with CAMU Placement Survey 56,834 cy

| | | Estimated Waste at Completion (cy) | % Complete |
|---------------------------------------|--|------------------------------------|------------|
| Cumulative Total To Date All Phases = | | 3,143,054 cy | 108.4% |

Geosynthetics Placed

| Phase I (complete) | Previous | Placed | Cumulative Placed |
|---------------------|----------|--------|-------------------|
| GCL | 307,372 | 0 | 307,372 |
| Geomembrane | 307,372 | 0 | 307,372 |
| Geocomposite | 307,372 | 0 | 307,372 |
| Geotextile | 69,340 | 0 | 69,340 |
| Phase II (complete) | | | |
| GCL | 498,468 | 0 | 498,468 |
| Geomembrane | 498,468 | 0 | 498,468 |
| Geocomposite | 520,592 | 0 | 520,592 |
| Geotextile | 0 | 0 | 0 |
| Phase IIIA | | | |
| GCL | 221,000 | 0 | 221,000 |
| Geomembrane | 221,000 | 0 | 221,000 |
| Geocomposite | 221,000 | 0 | 221,000 |
| Geotextile | 20,000 | 0 | 20,000 |
| Phase IIIB | | | |
| GCL | 340,535 | 0 | 340,535 |
| Geomembrane | 340,535 | 0 | 340,535 |
| Geocomposite | 340,535 | 0 | 340,535 |
| Geotextile | 50,000 | 0 | 50,000 |
| Phase IV | | | |
| GCL | 459,942 | 0 | 459,942 |
| Geomembrane | 459,942 | 0 | 459,942 |
| Geocomposite | 459,952 | 0 | 459,952 |
| Geotextile | 12,390 | 0 | 12,390 |
| Phase V | | | |

DAILY PRODUCTION & QUALITY CONTROL REPORT

| Project No./Contract No. | Project Title / Location | Day of Report | Report No. |
|--------------------------|---|---------------|------------|
| 6389 | BRC Eastside Common Areas Soils Remediation | 01-Feb-10 | 559 |
| | | | |

| | | | |
|--------------|---------|---|---------|
| GCL | 558,653 | 0 | 558,653 |
| Geomembrane | 558,653 | 0 | 558,653 |
| Geocomposite | 558,653 | 0 | 558,653 |
| Geotextile | 15,925 | 0 | 15,925 |

BMI North

| | | | |
|--------------|-----------|---|-----------|
| GCL | 1,111,468 | 0 | 1,111,468 |
| Geomembrane | 1,111,468 | 0 | 1,111,468 |
| Geocomposite | 1,111,468 | 0 | 1,111,468 |

BMI South

| | | | |
|--------------|---------|---|---------|
| GCL | 177,000 | 0 | 177,000 |
| Geomembrane | 177,000 | 0 | 177,000 |
| Geocomposite | 177,000 | 0 | 177,000 |

Debris Storage Area (complete)

| | | | |
|-------------|--------|---|--------|
| Geomembrane | 12,000 | 0 | 12,000 |
|-------------|--------|---|--------|

CAMU Cover

| | | | |
|--------------|---------|--------|---------|
| GCL | 788,514 | 23,886 | 812,400 |
| Geomembrane | 788,514 | 23,886 | 812,400 |
| Geocomposite | 741,800 | 70,600 | 812,400 |

| | | Total Geosynthetics for CAMU Basic Scope (\$f) | % Complete of Basic Scope | Total Geosynthetics for CAMU Basic Scope +Option Scope | % Complete of Basic Scope + Option Scope |
|--|-----------|--|---------------------------|--|--|
| Geosynthetic System Cumulative Total To Date All CAMU Phases | 4,498,838 | 4,151,232 | 88.8% | 6,534,075 | 68.9% |

HEALTH & SAFETY

| Description of Health & Safety Actions Taken Today / Safety Inspections Conducted | |
|---|--|
| | |

Safety Topic:

Eastside Day: Discussed: Housekeeping, trucks, equipment and site.
CAMU Day: Discussed: Housekeeping, trucks, equipment and site.
Night shift CAMU & Eastside: Discussed: Coming to work prepared to work.

CONSTRUCTION QUALITY ASSURANCE & QUALITY CONTROL

Description of Quality Control Actions Taken Today / Quality Inspections Conducted

Daily CQA Summary.

Monitored waste placement from the eastside to the CAMU on the day shift.
Monitored waste placement from the eastside to the CAMU on the night shift.
Monitored the installation of geosynthetics.
Monitored installation of final cover soils.

ISSUES AND/OR ITEMS OF DISCUSSION

On the Eastside, a Burrowing Owl was sited in work zone. Area was cordoned off and notifications were made.

SITE VISITORS

[illegible]

Report Prepared By / Title

Richard Laubinger, Construction Manager

Date Prepared

1-Feb-10

Signature _____

Weather Table

| | |
|-----------------------|---|
| Sunny/Clear |  |
| Sunny / Party Cloudy |  |
| Cloudy / Partly Sunny |  |
| Cloudy |  |
| Overcast |  |
| Light Rain |  |
| Rain |  |
| Thunderstorms |  |
| Snow |  |

Basic Remediation Company

875 West Warm Springs Road
Henderson, Nevada 89011

DAILY PRODUCTION & QUALITY CONTROL REPORT

| Project No./Contract No. | Project Title / Location | Day of Report | Report No. |
|--------------------------|---|---------------|------------|
| 6389 0 | BRC Eastside Common Areas Soils Remediation 0 | 01-Feb-10 | 559 |

DAILY PHOTO LOG

Photo 1



CAMU: Phase V.

Photo 2



CAMU: Phase IIIB.

Photo 3



CAMU: Phase I, Phase II and Phase IIIB.

Photo 4



CAMU: Phase I, Phase II and Phase IIIB.